

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011480/KBS3Q2
Date: 11/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900085736	
Claimant Vehicle No :	SKA3127M	Insured Vehicle No :	SML425R	
Date of Loss:	21/10/2020	Nature of Claim:	TP	Claim No: 4720858074SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA3127M		
Make & Model:	BMW X6, 3.0 35i (A)	Engine No:	06717497N55B30A
Reg. Date:	16/02/2011 (Man. Year: 2010)	Chassis No:	WBAFG22070LL80464
Colour:	Metallic Beige	Odometer:	179918 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/50 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	760.00	340.00	30.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,100.00	760.00	340.00	30.91
+ GST 7.00/7.00% (S\$)	77.00	53.20	23.80	30.91

Nett Amount (S\$)	1,177.00	813.20	363.80	30.91
+ Loss of Use (3.0 x S\$140.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,240.65		
Global Sum Settlement (S\$)		1,200.00		

INSPECTION

Date of Assignment: 23/10/2020

Date Inspected: 04/11/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Lim Tan Motor Pte Ltd (HQ)
 Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT	New	800.00	660.00
2	LABOUR CHARGES	New	300.00	100.00
Gross Labour Cost (S\$)			1,100.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >