

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011481/EBS3Q2
Date: 19/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100024768
Claimant Vehicle No :	SGT2357U	Insured Vehicle No :	SGV1405K
Date of Loss:	22/10/2020	Nature of Claim:	TP
		Claim No:	4779373972SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT2357U	Engine No:	LDA22020284
Make & Model:	HONDA CIVIC, 1.3 IMA (A)	Chassis No:	JHMF36207S201743
Reg. Date:	04/04/2007 (Man. Year: 2007)	Odometer:	207200 km
Colour:	Silver		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,664.60	2,294.48	5,370.12	70.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	1,750.00	2,110.00	54.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,524.60	4,044.48	7,480.12	64.91
Approved Total (Overridden) (S\$)		3,250.00		

Nett Amount (S\$)	11,524.60	3,250.00	8,274.60	71.80
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,126.45		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment: 23/10/2020

Date Inspected: 26/10/2020

Inspected At:

Nineteen Autowerks Pte Ltd (HQ)
 BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE
 Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	825.20 FL	*638.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Broken	137.00 FL	*137.00 FL
3	1		*BOOTLID	Dented	925.50 FL	*690.00 FL
4	1		*BOOTLID LOGO	Necessary	98.00 FL	*78.00 FL
5	1		*BOOTLID EMBLEM CIVIC	Necessary	74.20 FL	*65.00 FL
6	1		*BOOTLID EMBLEM HYBRID	Necessary	103.00 FL	*68.00 FL
7	2		*BOOTLID REFLECTOR	Not Necessary	745.60 FL	*- FL
8	1		*BOOTLID INNER LOCK	Jammed	297.60 FL	*194.00 FL
9	1		*BOOTLID INNER TRIM	Not Necessary	212.00 FL	*- FL
10	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	45.00 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Torn	197.60 FL	*197.60 FL
12	2		*TAILLAMP	Not Necessary	916.00 FL	*- FL
13	2		*TAILLAMP LOWER BRACKET	Not Necessary	139.20 FL	*- FL
14	1		*REAR END PANEL	Dented	826.40 FL	*316.00 FL
15	1		*REAR END PANEL TOP GARNISH	Crushed	188.90 FL	*72.00 FL
16	1		*SPARE TYRE PANEL	Repair	1,152.20 FL	*- FL
17	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	328.30 FL	*- FL
18	1		*EXHAUST PIPE ASSY	Not Necessary	996.30 FL	*- FL
19	3		*EXHAUST MOUNTING	Not Necessary	204.00 FL	*- FL
20	1		*SUNDRIES	Necessary	60.00 FS	*30.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	2		*SET BOOTLID REFLECTOR CLIPS	Not Necessary	50.00 FS	*- FS
23	2		*BOOTLID REFLECTOR SEAL	Not Necessary	50.00 FS	*- FS
24	1		*BOOTLID SEALANT	Necessary	80.00 FS	*30.00 FS
25	2		*SET TAILLAMP CLIPS	Not Necessary	60.00 FS	*- FS
26	2		*TAILLAMP SEAL	Not Necessary	60.00 FS	*- FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	35.00 FS	*10.00 FS
28	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
29	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
30	1		*REVERSE SENSOR WITH MODULE	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,347.00	2,785.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,682.40	491.12
Total Parts (\$\$)	7,664.60	2,294.48

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA	New	1,800.00	800.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	30.00
3	R&R INTERIOR UPHOLSTERY	New	200.00	30.00
4	R&R BOOTLID COMPONENT	New	100.00	30.00
5	R&R EXHAUST PIPE	New	200.00	0.00
6	R&R REVERSE SENSOR AND CHECK	New	80.00	30.00
7	TO APPLY UNDERCOATING FOR RUST PROOFING	New	200.00	30.00
8	SPRAY PAINTING ON ACCIDENT AREA	New	1,200.00	800.00
Gross Labour Cost (S\$)			3,860.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >