

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20011483/KGS3Q2

**Date:** 28/01/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> ES3383R	<b>Insured Vehicle No :</b>	SH8575M
Date of Loss: 21/10/2020	Nature of Claim: TP	Claim No: MCT20100354

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>ES3383R</b>	
Make & Model:	LEXUS RX270, 2.7 (A)	Engine No: 1AR0776588
Reg. Date:	01/01/2013 (Man. Year: 2013)	Chassis No: JTJZA11A302018933
Colour:	Metallic Maroon	Odometer: 87835 km
Engine Capacity:	2672 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,637.51	4,356.45	1,281.06	22.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,695.00	930.00	765.00	45.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,332.51</b>	<b>5,286.45</b>	<b>2,046.06</b>	<b>27.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,332.51</b>	<b>4,200.00</b>	<b>3,132.51</b>	<b>42.72</b>
<b>+ Loss of Use (4.0 x S\$120.00/day) (S\$)</b>		480.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,687.45</b>		

### INSPECTION

Date of Assignment:	28/10/2020	
Date Inspected:	28/10/2020 Inspected At:	Lim Yew Boo Spray Paint Co (HQ) NO. 176 SIN MING DRIVE #03-05, SIN MING IND EST Singapore 575645
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2020)
<b>Parts:</b>	M1-SUV	LEXUS RX270 2.7 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for ES3383R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	921.30 FL	*810.55 FL
2	1		*FRONT BUMPER RETAINER /LH	Distorted	101.30 FL	*101.30 FL
3	1		*FRONT FENDER /LH	Buckled	1,562.90 FL	*821.70 FL
4	1		*FRONT FENDER INNER SHIELD /LH	Distorted	510.80 FL	*311.30 FL
5	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	12.00 FL	*12.00 FL
6	1		*FRONT HEADLAMP ASSY/LH	Cracked	2,989.90 FL	*2,783.65 FL
7	1		*FRONT FOG LAMP COVER /LH	Serviceable	165.70 FL	*- FL
					<b>Sub Total (\$\$)</b>	<b>6,263.90</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>626.39</b>
					<b>Total Parts (\$\$)</b>	<b>5,637.51</b>
						<b>4,356.45</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION	New	55.00	20.00
2	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	30.00
3	TO CHECK COMPUTERISED WHEEL ALIGNMENT	New	120.00	0.00
4	TO REPAIR ,PANEL BEAT ,ALIGN ON AFFECTED FRT BONNET ,LEFT FRT DOOR & LABOUR TO REPLACE THE ABOVE MENTIONED PARTS	New	700.00	400.00
5	TO PUTTY ,PRIMER & SPRAY PAINT ON FRONT BUMPER ,LEFT FRT FENDER & TOUCH UP ON AFFECTED FRT BONNET USING 2K PAINT	New	700.00	480.00
<b>Gross Labour Cost (\$)</b>			<b>1,695.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >