



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2106089

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 31/08/2021
Reference CC4/FCI20011485/Aes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLC 7784S
Insured Veh. SHA 8605C
Claim No. D20004258MFSH
Policy No. D-20094921MFSH
Accident Date 18/10/2020
Inspection Date 26/10/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20011485/Aes3q2	
			Date: 31/08/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 8605C	Veh. Inspected	SLC 7784S
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D20004258MFSH	Excess (\$)	0.00
	Assign From	ERIC	Assign Date	23/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	RU11113365	Colour	WHITE
	Odometer	209077 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	ROADSTONE	6 mm
	L/H Front Tyre	215/60 R16	ROADSTONE	6 mm
	R/H Rear Tyre	215/60 R16	ROADSTONE	6 mm
	L/H Rear Tyre	215/60 R16	ROADSTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/10/2020	Inspection Date	26/10/2020
	Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 7784S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	AIR DUCT	NOT NECESSARY	127.50	-
1	FRONT AIRCON CONDENSER	BENT	568.10	568.10
1	FRONT AIRCON CONDENSER ALUMINIUM PIPE	NOT NECESSARY	195.00	-
1	FRONT AIRCON CONDENSER DISCHARGE PIPE	NOT NECESSARY	210.00	-
1	FRONT AIRCON FAN BLADE	NOT NECESSARY	57.70	-
1	FRONT AIRCON FAN COWLING	NOT NECESSARY	125.00	-
1	FRONT AIRCON FAN MOTOR	NOT NECESSARY	295.00	-
1	FRONT BONNET	DENTED	892.30	892.30
2	FRONT BONNET HINGES L/R @\$48.50	BENT	97.00	97.00
2	FRONT BONNET INNER RUBBER GUIDE STOPPER L/R @ \$23.80	NOT NECESSARY	47.60	-
2	FRONT BONNET INNER SIDE MOULDING L/R @\$37.50	NOT NECESSARY	-	-
2	FRONT BONNET INNER SIDE MOULDING L/R @\$37.50	NOT NECESSARY	75.00	-
2	FRONT BONNET INNER TOP MOULDING L/R @\$23.00	NOT NECESSARY	46.00	-
1	FRONT BONNET INSULATOR	NOT NECESSARY	122.30	-
1	FRONT BONNET MECHANISM LOCK	DAMAGED	95.00	95.00
1	FRONT BUMPER	DEFORMED	801.70	801.70
2	FRONT BUMPER FOGLAMP BRACKET L/R @\$49.00	N/S CRACKED	98.00	49.00
2	FRONT BUMPER FOGLAMP GARNISH L/R @\$45.00	N/S CRACKED	90.00	45.00
2	FRONT BUMPER FOGLAMP L/R @\$327.70	N/S CRACKED	655.40	327.70
1	FRONT BUMPER LOWER GRILLE	CRACKED	77.50	77.50
1	FRONT BUMPER LOWER LID	DISTORTED	381.00	381.00
1	FRONT BUMPER REINFORCEMENT	DENTED	321.00	321.00
2	FRONT BUMPER SIDE RETAINER L/R @\$20.60	N/S DAMAGED	41.20	20.60
1	FRONT GRILLE	CRACKED	351.80	351.80
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	23.40	23.40
1	FRONT GRILLE CENTER BRACKET	CRACKED	76.00	76.00
2	FRONT GRILLE CHROME MOULDING L/R @\$98.00	N/S CUT	196.00	98.00
1	FRONT GRILLE OUTER COVER	CRACKED	421.00	421.00
1	FRONT GRILLE TOP GARNISH	DEFORMED	85.00	85.00
2	FRONT HEADLAMP L/R @\$1784.50	CRACKED	3,569.00	3,569.00

Report Ref No. CC4/FCI20011485/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT HEADLAMP LOWER BRACKET L/R @\$35.00	CRACKED	70.00	70.00
2	FRONT HEADLAMP SIDE BRACKET L/R @\$35.00	N/S CRACKED	70.00	35.00
1	FRONT HORN	NOT NECESSARY	110.50	-
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	580.00	-
1	FRONT LH FENDER ARCH GARNISH	CRACKED	220.00	220.00
1	FRONT LH FENDER INNER SHIELD	TORN	130.00	130.00
1	FRONT OUTSIDE TEMPERATURE SENSOR	NOT NECESSARY	80.00	-
1	FRONT SUPPORT PANEL	DENTED	576.20	576.20
1	RADIATOR (AUTO)	WARPED	1,376.60	1,376.60
2	RADIATOR BOTTOM MOUTING L/R @\$14.50	NOT NECESSARY	29.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	57.70	-
1	RADIATOR FAN COWLING	NOT NECESSARY	125.00	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	298.00	-
2	RADIATOR SIDE GUIDE L/R @\$31.60	N/S DEFORMED	63.20	31.60
2	RADIATOR TOP MOUNTING L/R @\$10.50	NOT NECESSARY	21.00	-
	LESS 20% DISCOUNT		-2,789.74	-2,147.90
			11,158.96	8,591.60
	<u>SPECIAL NETT ITEMS</u>			
1	BATTERY (SN)	NOT NECESSARY	260.00	-
1	SET FRONT BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
2	SET FRONT FENDER ARCH GARNISH CLIPS @\$30.00 (SN)	NECESSARY	60.00	20.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	25.00
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	40.00	30.00
1	FRONT NUMBER PLATE (SN)	CUT	25.00	25.00
1	FRONT NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	40.00
			695.00	170.00
	<u>LABOUR</u>			
	TO REMOVE ,CHARGE AIR CON PARTS ,VACUUM ,REFILL AIR CON GAS .		140.00	120.00

Report Ref No. CC4/FCI20011485/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR).		80.00	30.00
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	400.00	-
	TO RE-SPRAY PAINTING ON THE FRONT BONNET ,FRONT SUPPORT PANEL ,FRONT FENDER (L/R) AND FRONT BUMPER .		1,200.00	900.00
	TO PROVIDE LABOUR , WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF FRONT LH FENDER .		1,000.00	800.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			2,940.00	1,910.00
GRAND TOTAL			14,793.96	10,671.60

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,500.00
---	--	--	-----------------

Report Ref No. CC4/FCI20011485/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 7784S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 7784S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 7784S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 7784S

RE-INSPECTION

