

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011488/R1TD3E2

Date: 11/12/2020

REFERENCE

Insured/Claimant:	CHIA JIA JUN	Policy No:	1800147012
Date of Loss:	22/10/2020	Nature of Claim:	OD
		Claim No:	5379620708SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH1421R	Engine No:	G4FGJH713534
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5024571
Reg. Date:	14/01/2019 (Man. Year: 2018)	Odometer:	27731 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$74,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,880.40	5,927.60	1,952.80	24.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,080.00	5,740.00	2,340.00	28.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,960.40	11,667.60	4,292.80	26.90
+ GST 7.00/7.00% (\$\$)	1,117.23	816.73	300.50	26.90
Nett Amount (\$\$)	17,077.63	12,484.33	4,593.30	26.90

INSPECTION

Date of Assignment:	23/10/2020	
Date Inspected:	23/10/2020 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER - RR BUMPER	Torn	651.00 FL	*651.00 FL
2	1		*COVER - RR BUMPER LWR	Torn	241.00 FL	*241.00 FL
3	1		*COVER - RR BUMPER UNDER, LH	Serviceable	33.00 FL	*- FL
4	1		*COVER - RR BUMPER FOG LAMP, LH	Serviceable	19.00 FL	*- FL
5	1		*COVER - RR BUMPER FOG LAMP, RH	Scratched	19.00 FL	*19.00 FL
6	1		*LAMP ASSY - SIDE T/SIGNAL, LH	Scratched	181.00 FL	*181.00 FL
7	1		*LAMP ASSY - SIDE T/SIGNAL, RH	Serviceable	181.00 FL	*- FL
8	1		*EXTN WIRING ASSY - BWS	Serviceable	207.00 FL	*- FL
9	1		*BEAM - RR BUMPER	Cracked	318.00 FL	*318.00 FL
10	1		*STAY - RR BUMPER LH	Bent	65.00 FL	*65.00 FL
11	1		*STAY - RR BUMPER RH	Bent	65.00 FL	*65.00 FL
12	1		*BRACKET - RR BEAM UPR MTG, LH	Serviceable	9.00 FL	*- FL
13	1		*BRACKET - RR BEAM UPR MTG, RH	Serviceable	9.00 FL	*- FL
14	1		*BRACKET RR BEAM LWR, CTR	Cracked	6.00 FL	*6.00 FL
15	2		*BRACKET - RR BEAM LWR MTG	Cracked	12.00 FL	*6.00 FL
16	1		*ANTENNA ASSY - SMARTKEY	Serviceable	46.00 FL	*- FL
17	1		*BRACKET ASSY - RR BPR SIDE UPR, L	Cracked	25.00 FL	*25.00 FL
18	1		*BRACKET - ASSY RR BPR SIDE UPR, R	Cracked	31.00 FL	*31.00 FL
19	1		*COVER - RR BUMPER UNDER, RH	Serviceable	33.00 FL	*- FL
20	1		*PANEL ASSY - TRUNK LID	Bent	1,297.00 FL	*1,297.00 FL
21	1		*HINGE ASSY - TRUNK LID, LH	Serviceable	97.00 FL	*- FL
22	1		*HINGE ASSY - TRUNK LID, RH	Serviceable	97.00 FL	*- FL
23	1		*LOGO ASSY - KIA SUB	Necessary	32.00 FL	*32.00 FL
24	1		*EMBLEM - CERATO	Necessary	28.00 FL	*28.00 FL
25	1		*W/STRIP - TRUNK LID 0PNG	Cut	100.00 FL	*100.00 FL
26	1		*LATCH ASSY - TRUNK LID	Cut	112.00 FL	*112.00 FL
27	1		*STRIKER ASSY - TRUNK LID	Serviceable	40.00 FL	*- FL
28	1		*TRIM ASSY - TRUNK LID	Cracked	202.00 FL	*202.00 FL
29	1		*LAMP ASSY - CENTER GARNISH	Cracked	690.00 FL	*690.00 FL
30	1		*LAMP ASSY - REAR COMB INSIDE, LH	Scratched	608.00 FL	*608.00 FL
31	1		*LAMP ASSY - REAR COMB OUTSIDE, LH	Serviceable	675.00 FL	*- FL
32	1		*LAMP ASSY - REAR COMB OUTSIDE, RH	Cracked	675.00 FL	*675.00 FL
33	1		*PANEL ASSY - BACK	Bent	324.00 FL	*324.00 FL
34	1		*TRIM ASSY - RR TRANSVERSE	Serviceable	41.00 FL	*- FL
35	1		*TRIM ASSY - RR TRANSVERSE	Serviceable	41.00 FL	*- FL
36	1		*PANEL ASSY - REAR FLOOR, RR	Buckled	219.00 FL	*219.00 FL
37	1		*GUARD - REAR WHEEL, LH	Serviceable	75.00 FL	*- FL
38	1		*GUARD - REAR WHEEL, RH	Serviceable	75.00 FL	*- FL
39	1		*MUFFLER ASSY - REAR	Serviceable	757.00 FL	*- FL
40	1		*PROTECTOR - HEAT REAR	Bent	136.00 FL	*136.00 FL
41	1		*RR NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
42	1		*REVERSE SENSOR	Faulty	220.00 FS	*220.00 FS
43	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
44	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
45	1		*SILENCER, FLOOR	Necessary	13.00 FL	*13.00 FL
46	1		*CLIPS(X10)	Necessary	10.00 FL	*10.00 FL
47	1		*TRIM ASSY-LUGGAGE SIDE RH	Cracked	200.00 FL	*200.00 FL
48	1		*LAMP ASSY-REAR COMB INSIDE, RH	Scratched	608.00 FL	*608.00 FL
49	1		*PANEL ASSY-RR COMB LAMP HSG, RH	Buckled	135.00 FL	*135.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$)	9,768.00	7,327.00
			- List Item Discount on L Items 20.00/20.00% (\$)		1,887.60	1,399.40
				Total Parts (\$)	7,880.40	5,927.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW RR BUMPER, RR END PNL, BOOTLID & RR FLR PNL REPAIR LHR FENDER, RHR FENDER & RR CHASSIS.	New	3,200.00	1,800.00
2	RESPRAY RR BUMPER, RR END PNL, RR FLR PNL, BOOTLID, LHR FENDER RHR FENDER & RR CHASSIS.	New	2,450.00	1,750.00
3	REMOVE & REFIT BOOTLID COMPONENT.	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM, CARPET, SEAT TO FACILITATE REPAIR.	New	120.00	120.00
5	REMOVE & REFIT FUEL TANK ASSY TO GIVE WAY FOR REPAIR.	New	200.00	200.00
6	REMOVE & REFIT RR EXHAUST MUFFLER ASSY.	New	200.00	0.00
7	CHECK WIRING ELECTRICAL SYSTEM.	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS.	New	80.00	40.00
10	REMOVE & REFIT REVERSE SENSOR.	New	60.00	60.00
11	REPLACE REAR FLOOR PANEL, REPAIR REAR CHASSIS, & LH REAR FENDER	New	800.00	800.00
12	RESPRACY ON REAR CHASSIS & LK REAR FENDER TO THE SAME	New	700.00	700.00
Gross Labour Cost (\$\$)			8,080.00	5,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >