

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20011522/DSD3Q2**Date:** 28/10/2020REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001452831
Claimant		
Vehicle No : SKW5935T	Insured Vehicle No :	SKH6144G
Date of Loss: 25/09/2020	Nature of Claim:	TP
		Claim No: 248258

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW5935T		
Make & Model:	mitsubishi LANCER, 1.6 EX AT LED TAIL LAMP (A)	Engine No:	4A92CC2673
Reg. Date:	05/11/2015 (Man. Year: 2015)	Chassis No:	JMYSRCY1AFU005589
Colour:	Red	Odometer:	84933 km
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,591.00	0.00	3,591.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	600.00	1,120.00	65.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,311.00	600.00	4,711.00	88.70

INSPECTION

Date of Assignment:	22/10/2020	
Date Inspected:	23/10/2020	Inspected At: Alfred Auto Services & Supplies (HQ) Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2 Singapore 569538
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2020)	
Parts: 143	MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKW5935T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Repair	898.00 F	*- F	
2	10		*FRONT BUMPER CLIPS	Serviceable	50.00 F	*- F	
3	1		*FRONT BUMPER BEAM	Not Necessary	298.00 F	*- F	
4	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	135.00 F	*- F	
5	2		*FRONT BUMPER SIDE PROTER	Not Necessary	216.00 F	*- F	
6	1		*FRONT FOG LAMP	Not Necessary	488.00 F	*- F	
7	1		*FRONT FOG LAMP GARNISH	Not Necessary	99.00 F	*- F	
8	1		*FRONT HEAD LAMP ASSY	Not Necessary	899.00 F	*- F	
9	1		*FRONT RH FENDER	Not Necessary	508.00 F	*- F	
					Total Parts (\$)	3,591.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	120.00	0.00
2	TO KNOCKING ,STRAIGHTEN REPAIR & RENEW ALL ACCIDENT DAMAGED AFFECTED AREA	New	800.00	200.00
3	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA (2 COLOUR)	New	800.00	400.00
			Gross Labour Cost (S\$)	600.00
			1,720.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >