

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20011523/ETD3Q2

Date: 05/11/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant

Vehicle No : SLB5441A

Insured Vehicle No : SLP8066G

Date of Loss: 21/10/2020

Nature of Claim: TP

Claim No: 630114

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB5441A**

Make & Model: AUDI A5, 2.0 SPORTBACK (A)

Engine No: CDN105397

Reg. Date: 05/04/2011 (Man. Year: 2010)

Chassis No: WAUZZZ8T5AA058047

Colour: White

Odometer: 128610 km

Engine Capacity: 1984 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18

Rear Tyre Size: 245/40R18

Front Left Side: Continental 5 mm

Rear Left Side: Continental 5 mm

Front Right Side: Continental 5 mm

Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,130.31	10,841.36	10,288.95	48.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	2,480.00	1,910.00	43.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,520.31	13,321.36	12,198.95	47.80
Approved Total (Overridden) (\$\$)		10,650.00		
Nett Amount (\$\$)	25,520.31	10,650.00	14,870.31	58.27

INSPECTION

Date of Assignment: 23/10/2020

Date Inspected: 26/10/2020 Inspected At:

Nineteen Autowerks Pte Ltd (HQ)
BLK 15 KAKI BUKIT ROAD 4 #01-53
BARTLEY BIZ CENTRE
Singapore 417808

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2020)
Parts:	143	AUDI A5 2.0 SPORTBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5441A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR RH	Not Necessary	1,985.00 FL	*- FL
2	1	*FRONT DOOR INNER LOCK RH	Not Necessary	374.00 FL	*- FL
3	1	*FRONT DOOR WEATHERSTRIP RH	Not Necessary	219.00 FL	*- FL
4	1	*DOOR CENTRE PILLAR OUTER RH	Not Necessary	694.00 FL	*- FL
5	1	*REAR DOOR RH	Dented	1,912.00 FL	*1,912.00 FL
6	1	*REAR DOOR OUTER HANDLE RH	Jammed	119.00 FL	*119.00 FL
7	1	*REAR DOOR OUTER MOULDING RH	Bent	142.00 FL	*142.00 FL
8	1	*REAR DOOR INNER LOCK RH	Jammed	346.00 FL	*346.00 FL
9	1	*REAR DOOR LOCK ACTUATOR RH	Not Necessary	417.00 FL	*- FL
10	1	*REAR DOOR WEATHERSTRIP RH	Necessary	192.00 FL	*192.00 FL
11	2	*REAR DOOR HINGES RH	Bent	216.00 FL	*216.00 FL
12	1	*REAR DOOR CHECKER RH	Not Necessary	155.00 FL	*- FL
13	1	*REAR DOOR TRIMBOARD RH	Broken	487.00 FL	*487.00 FL
14	1	*REAR DOOR REGULATOR ASSY RH	Bent	388.00 FL	*388.00 FL
15	1	*REAR DOOR INSULATOR SHEET RH	Not Necessary	172.00 FL	*- FL
16	1	*REAR FENDER RH	Dented	2,141.00 FL	*2,141.00 FL
17	1	*REAR FENDER QUARTER GLASS W MOULDING RH	Necessary	294.00 FL	*294.00 FL
18	1	*REAR FENDER INNER SHIELD RH	Torn	167.00 FL	*167.00 FL
19	1	*REAR WINDSCREEN MOULDING	Necessary	214.00 FL	*214.00 FL
20	1	*TAILLAMP RH	Not Necessary	628.00 FL	*- FL
21	1	*REAR SHOCK ABSORBER RH	Not Necessary	565.00 FL	*- FL
22	1	*REAR LOWER ARM RH	Not Necessary	587.00 FL	*- FL
23	1	*REAR TRAILING ARM RH	Not Necessary	442.00 FL	*- FL
24	1	*REAR KNUCKLE ARM RH	Not Necessary	706.00 FL	*- FL
25	1	*REAR KNUCKLE ARM BEARING RH	Jammed	385.00 FL	*385.00 FL
26	1	*REAR BUMPER	Broken	1,765.80 FL	*1,765.80 FL
27	2	*REAR BUMPER SIDE RETAINER	Broken	435.00 FL	*435.00 FL
28	1	*BOOTLID (NPA)	Not Necessary	0.00 FL	*- FL
29	1	*BOOTLID (NPA) LOGO	Not Necessary	103.00 FL	*- FL
30	1	*BOOTLID EMBLEM A5	Not Necessary	77.00 FL	*- FL
31	1	*BOOTLID EMBLEM 2.0T	Not Necessary	77.00 FL	*- FL
32	1	*REAR SHOCK ABSORBER LH	Not Necessary	565.00 FL	*- FL
33	1	*REAR LOWER ARM LH	Not Necessary	587.00 FL	*- FL
34	1	*REAR TRAILING ARM LH	Not Necessary	442.00 FL	*- FL
35	1	*REAR KNUCKLE ARM LH	Not Necessary	706.00 FL	*- FL
36	1	*REAR KNUCKLE ARM BEARING LH	Jammed	385.00 FL	*385.00 FL
37	1	*SUNDRIES	Necessary	60.00 FS	*30.00 FS
38	1	*SET FRONT DOOR TRIMBOARD CLIPS	Not Necessary	45.00 FS	*- FS
39	1	*FRONT DOOR SEALANT	Not Necessary	80.00 FS	*- FS
40	1	*SET REAR DOOR TRIMBOARD CLIPS RH	Necessary	45.00 FS	*20.00 FS
41	1	*REAR DOOR SEALANT RH	Necessary	80.00 FS	*30.00 FS
42	1	*SET REAR FENDER INNER SHIELD CLIPS RH	Necessary	30.00 FS	*20.00 FS
43	1	*SET REAR FENDER INNER TRIM CLIPS RH	Necessary	45.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SET TAILLAMP CLIPS RH	Not Necessary	25.00 FS	*- FS
45	1		*TAILLAMP SEAL RH	Not Necessary	25.00 FS	*- FS
46	1		*REAR ALLOY RIM RH	Cut	980.00 FS	*700.00 FS
47	1		*REAR TYRE RH	Not Necessary	260.00 FS	*- FS
48	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
49	1		*REAR ALLOY RIM LH	Cut	980.00 FS	*700.00 FS
50	1		*REAR TYRE LH (70%)	Torn	260.00 FS	*182.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,084.80	11,320.80
- List Item Discount on L Items 5.00/5.00% (\$\$)	954.49	479.44
Total Parts (\$\$)	21,130.31	10,841.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA	New	1,200.00	1,000.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	30.00
3	R&R INTERIOR UPHOLSTERY	New	200.00	50.00
4	R&R RH FRONT DOOR COMPONENT	New	80.00	0.00
5	R&R RH REAR DOOR COMPONENT	New	80.00	50.00
6	R&R REAR WINDSCREEN	New	180.00	120.00
7	R&R RH REAR TYRE AND BALANCING	New	60.00	60.00
8	R&R RH REAR UNDERCARRIAGE COMPONENT	New	300.00	80.00
9	R&R LH REAR TYRE AND BALANCING	New	60.00	0.00
10	R&R LH REAR UNDERCARRIAGE COMPONENT	New	300.00	80.00
11	TO CONDUCT ALL WHEEL ALIGNMENT	New	150.00	60.00
12	TO APPLY UNDERCOATING FOR RUST ROOFING	New	200.00	30.00
13	SPRAY PAINTING ON ACCIDENT AREA	New	1,500.00	920.00
Gross Labour Cost (\$\$)			4,390.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >