

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20011525/KTD3Q2
Date: 14/06/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713
Claimant Vehicle No :	SMD2261A	Insured Vehicle No :	SLQ7615Z
Date of Loss:	23/10/2020	Nature of Claim:	TP
		Claim No:	630149

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD2261A	Engine No:	L13B11031016
Make & Model:	HONDA JAZZ, 1.3 CVT (A)	Chassis No:	JHMGK3850JX226639
Reg. Date:	08/08/2018 (Man. Year: 2018)	Odometer:	25928 km
Colour:	Metallic Grey		
Engine Capacity:	1318 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,683.20	11,408.96	1,274.24	10.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	3,760.00	500.00	11.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,943.20	15,168.96	1,774.24	10.47
+ GST 7.00/7.00% (S\$)	1,186.02	1,061.83	124.19	10.47

Nett Amount (S\$)**18,129.22****16,230.79****1,898.43****10.47**INSPECTION

Date of Assignment: 23/10/2020

Date Inspected: 26/10/2020

Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)
10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT
Singapore 568047

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2021)
Parts:	144	HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD2261A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Cracked	517.60 FL	*517.60 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	228.50 FL	*228.50 FL
3	1		*FRONT BUMPER NUMBER PLATE GARNISH	Dented	49.80 FL	*49.80 FL
4	1		*FRONT BUMPER TOW HOOK COVER	Missing	14.80 FL	*14.80 FL
5	1		*FRONT BUMPER LH FOG LAMP COVER	Cut	35.00 FL	*35.00 FL
6	2		*FRONT BUMPER LH SIDE RETAINER	Distorted	24.00 FL	*24.00 FL
7	1		*FRONT BUMPER CENTRE LOWER GRILLE	Dented	137.90 FL	*137.90 FL
8	2		*FRONT BUMPER CENTRE LOWER GRILLE SIDE GARNISH	Distorted	26.00 FL	*26.00 FL
9	5		*FRONT BUMPER CLIP	Necessary	19.50 FL	*19.50 FL
10	1		*BONNET	Bent	550.20 FL	*550.20 FL
11	1		*BONNET LH HINGE	Distorted	31.20 FL	*31.20 FL
12	1		*BONNET LH SIDE GARNISH	Distorted	24.00 FL	*24.00 FL
13	1		*FRONT GRILLE HOUSING	Cracked	253.80 FL	*253.80 FL
14	1		*FRONT GRILLETOP CHROME	Dented	224.10 FL	*224.10 FL
15	1		*FRONT GRILLE LOGO	Necessary	27.40 FL	*27.40 FL
16	1		*FRONT GRILLE OUTER LOWER CHROME	Scratched	202.80 FL	*202.80 FL
17	3		*FRONT GRILLE CLIP	Necessary	11.10 FL	*11.10 FL
18	1		*HEADLAMP LH	Cracked	558.60 FL	*558.60 FL
19	1		*HEADLAMP LH LOWER BRACKET	Cracked	37.80 FL	*37.80 FL
20	1		*FRT SUPPORT PANEL	Bent	420.00 FL	*420.00 FL
21	1		*AIR RESONATOR	Cracked	120.80 FL	*120.80 FL
22	1		*FRONT LH FENDER	Buckled	483.50 FL	*483.50 FL
23	1		*FRONT LH FENDER EXTENSION ARM	Bent	115.00 FL	*115.00 FL
24	1		*FRONT LH FENDER SIDE ARM	Distorted	52.00 FL	*52.00 FL
25	2		*FRONT FENDER INNER SHIELD	Cracked	143.00 FL	*143.00 FL
26	12		*FRONT FENDER INNER SHIELD CLIP	Necessary	46.80 FL	*46.80 FL
27	1		*FRONT LH FENDER INNER PANEL INNER	Bent	295.00 FL	*295.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*DASHBOARD ASSY	Torn	718.50 FL	*718.50 FL
29	1		*FRONT PASSENGER AIRBAG	Burst	2,236.80 FL	*2,236.80 FL
30	1		*STEERING AIRBAG	Burst	1,640.30 FL	*1,640.30 FL
31	1		*STEERING SPIRAL CABLE	Necessary	289.30 FL	*289.30 FL
32	1		*AIR BAG ECU	Necessary	886.70 FL	*886.70 FL
33	1		*FRONT AIRBAG SENSOR	Necessary	157.50 FL	*157.50 FL
34	2		*FRONT SEAT BELT	Jammed	993.60 FL	*993.60 FL
35	2		*FRONT SEAT BELT LOWER CENTRE GARNISH	Mtg Distorted	103.80 FL	*103.80 FL
36	1		*FRONT LH RIM 15	Dented	957.60 FL	*957.60 FL
37	1		*FRONT LH KNUCKLE ARM	Bent	220.60 FL	*220.60 FL
38	1		*FRONT LH WHEEL HUB	Serviceable	138.30 FL	*- FL
39	1		*FRONT LH WHEEL BEARING	Necessary	123.30 FL	*123.30 FL
40	1		*FRONT LH LOWER ARM	Distorted	151.80 FL	*151.80 FL
41	1		*FRONT LH SHOCK ABSORBER	Serviceable	340.80 FL	*- FL
42	1		*FRONT LH STAY LINKAGE	Distorted	49.80 FL	*49.80 FL
43	1		*REAR BUMPER	Bent / Distorted	693.70 FL	*693.70 FL
44	1		*REAR BUMPER LH SIDE GARNISH	Serviceable	38.00 FL	*- FL
45	1		*REAR BUMPER LH SIDE RETAINER	Cracked	16.90 FL	*16.90 FL
46	5		*REAR BUMPER LH INNER SHIELD CLIPS	Necessary	19.50 FL	*19.50 FL
47	1		*REAR BUMPER CENTRE GARNISH	Serviceable	65.00 FL	*- FL
48	1		*REAR LH FENDER INNER SHIELD	Distorted	85.80 FL	*85.80 FL
49	1		*REAR LH FENDER AIR GRILLE	Dented	28.00 FL	*28.00 FL
50	1		*LH TAILLAMP	Serviceable	244.60 FL	*- FL
51	1		*REAR END PANEL	Repair	328.60 FL	*- FL
52	1		*FRONT NUMBER PLATE	Necessary	35.00 FS	*35.00 FS
53	1		*COOLANT	Necessary	35.00 FS	*35.00 FS
54	1		*FRONT LH TYRE 15 (80%)	Cut	150.00 FS	*120.00 FS
55	1		*SET REVERSE SENSOR (4 PCS)	Serviceable	280.00 FS	*- FS
56	1		*REAR END PANEL SEALANT	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,719.00	14,213.70
- List Item Discount on L Items 20.00/20.00% (S\$)	3,035.80	2,804.74
Total Parts (S\$)	12,683.20	11,408.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	50.00	50.00
2	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
3	REMOVE & REFIX FRT BUMPER & ATTACHMENTS BONNET & ATTACHMENTS GRILLE HEADLAMP FRT LH FENDER.TO CUT WELD & RENEW FRT SUPPORT PANEL ,FRT LH FENDER INNER & OUTER PANEL ,KNOCKING & REPAIR FRT CHASSIS FRAME & REALIGN FRT LH DOOR THE SAME	New	1,000.00	900.00
4	PUTTY & RESPRAY FRT BUMPER ,BONNET ,FRT LH FENDER & INNER PANEL ,FRT SUPPORT PANEL ,FRT LH DOOR ,FRT CHASSIS FRAMES & ALL AFFECTED AREAS	New	950.00	900.00
5	REMOVE & REFIX FRT DASHBOARD TO FACILITATE REPAIR	New	250.00	250.00
6	REMOVE & REFIX AIRBAG ECU ,FRT SEAT BELTS STEERING & PASSENGERS AIRBAGS & RESET FAULT CODE	New	350.00	280.00
7	REMOVE & REFIX FRT LH UNDERCARRIAGE RIM & REALIGN THE SAME	New	150.00	150.00
8	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
9	REMOVE & REFIX REAR BUMPER & ATTACHMENTS ,TAILLAMP ,TO CUT ,WELD & RENEW REAR END PANEL ,KNOCKING & REPAIR REAR LH FENDER & REALIGN THE SAME	New	600.00	400.00
10	PUTTY & RESPRAY REAR BUMPER & REVERSE SENSORS ,REAR END PANEL ,REAR LH FENDER &ALL AFFECTED AREAS	New	600.00	550.00
11	RUSTPROOFING	New	150.00	120.00
Gross Labour Cost (\$\$)			4,260.00	3,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >