

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 561L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	IONIQVC COVER-RR BUMPER	TO REPAIR SEE LABOUR	459.40	-
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	IONIQV2-4 MOULDING ASSY-R	CRUSHED	451.25	451.25
1	IONIQVC LAMP ASSY-REAR FO	BROKEN	201.50	201.50
1	REAR BUMPER LOWER CTR MOULDING	BROKEN	155.00	155.00
1	REAR BUMPER SIDE BRACKET RH	BROKEN	55.80	55.80
1	ANTENNA ASSY-SMARTKEY	BROKEN	40.50	40.50
	LESS 20% DISCOUNT		-277.09	-185.21
			1,108.36	740.84
	NETT ITEMS			
1	NO PLATE (S) WITH TRIM COV (N)	BROKEN	55.00	55.00
1	HYUNDAI REVERSE SENSOR AS (N)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-23.50	-5.50
			211.50	49.50
	SPECIAL NETT ITEMS			
1	IONIQVC PROTECTOR MAT (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
			250.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF IONIQVC COVER-RR BUMPER.		350.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
	CHECK ALL LIGHTING.		50.00	30.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	80.00	-
			730.00	550.00
	GRAND TOTAL		2,299.86	1,540.34

RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,540.34
---	--	--	----------

Report Ref No. NS/INC20011527/Etd3e2





Report Ref No. NS/INC20011527/Etd3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser