

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1695M**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	I40VC COVER ASSY-RR BUMPE	DENTED	1,106.00	1,106.00
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	I40VC COVER-RR BUMPER LWR	NOT NECESSARY	228.00	-
1	I40VC LAMP ASSY-RR COMB O LH (CRACKED)	NOT CONSISTENT WITH THE IMPACT	697.80	-
	LESS 20% DISCOUNT		-410.76	-225.60
			1,643.04	902.40
<b><u>NETT ITEMS</u></b>				
1	HYUNDAI REVERSE SENSOR AS (N)	NOT NECESSARY	135.70	-
	LESS 10% DISCOUNT		-13.57	-
			122.13	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		350.00	280.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
	CHECK ALL LIGHTING.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			770.00	540.00
<b>GRAND TOTAL</b>			<b>2,585.17</b>	<b>1,492.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,200.00</b>

Report Ref No. NS/INC20011528/Esd3e2


**CHEN TSUE YEE**

Automotive Assessor


**K.K.LAU CPT(RET)**

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.