

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315



Page No.:1 of 2

Reg. No: 52983356E GST Reg. No. 20-0405911-H

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8875Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	IONIQVC COVER-RR BUMPER	DENTED	459.40	459.40
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	IONIQV2-4 MOULDING ASSY-R	CRUSHED	451.25	451.25
1	IONIQVC LAMP ASSY-REAR FO	NOT NECESSARY	201.50	-
1	IONIQVC CAP-RR HOOK	NOT NECESSARY	98.80	-
1	IONIQVC MOULDING-REAR BUM	CRUSHED	155.00	155.00
1	IONIQVC EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	IONIQVC EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	ANTENNA ASSY SMARTKEY	BROKEN	40.50	40.50
1	REAR BUMPER REINFORCEMENT	BENT	294.80	294.80
1	REAR BUMPER STAY LH	BENT	138.10	138.10
1	REAR BUMPER STAY RH	BENT	138.10	138.10
	LESS 20% DISCOUNT		-411.01	-350.95
			1,644.04	1,403.80
	NETT ITEMS			
1	HYUNDAI REVERSE SENSOR AS (N)	BROKEN	180.00	180.00
1	NO PLATE (S) WITH TRIM COV (N)	BROKEN	55.00	55.00
1	APP LOGO REAR BONNET CTPL (N)	NECESSARY	40.00	40.00
1	(I40) REAR BOOT LOGO CTPL (N)	NECESSARY	30.00	30.00
1	(I40) REAR BOOT TEL NUMBER (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-33.50	-33.50
			301.50	301.50
	<u>LABOUR</u>			
	PANEL BEATING.		650.00	480.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			1,320.00	940.00

Report Ref No. NS/INC20011529/Esd3e2





	GRAND TOTAL			3,265.54	2,645.30
--	-------------	--	--	----------	----------

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,645.30
---	--	--	----------

Report Ref No. NS/INC20011529/Esd3e2



**Automotive Assessor** 



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser