

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011532/RIVF3E2

Date: 01/12/2020

REFERENCE

Insured/Claimant:	CHONG WEN HAO	Policy No:	1900117635	
Date of Loss:	23/10/2020	Nature of Claim:	OD	Claim No: 6886661073SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT1394X		
Make & Model:	KIA STONIC, 998cc (A)	Engine No:	G3LCKP067522
Reg. Date:	06/08/2019 (Man. Year: 2019)	Chassis No:	KNAD6811VL6319126
Colour:	Black	Odometer:	21615 km
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,812.00	6,769.20	1,042.80	13.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,360.00	5,160.00	3,200.00	38.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,172.00	11,929.20	4,242.80	26.24
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	15,872.00	11,629.20	4,242.80	26.73
+ GST 7.00/7.00% (\$\$)	1,111.04	814.04	297.00	26.73
Nett Amount (\$\$)	16,983.04	12,443.24	4,539.80	26.73

INSPECTION

Date of Assignment: 23/10/2020
Date Inspected: 26/10/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY - HEAD, LH	Cracked	1,845.00 FL	*1,845.00 FL
2	1		*LAMP ASSY - HEAD, RH	Broken	1,845.00 FL	*1,845.00 FL
3	1		*RESERVOIR & PUMP, ASSY - WASHER	Torn	152.00 FL	*152.00 FL
4	1		*PANEL ASSY - HOOD	Buckled	904.00 FL	*904.00 FL
5	1		*HINGE ASSY - HOOD, RH	Bent	43.00 FL	*43.00 FL
6	1		*HINGE ASSY - HOOD, LH	Bent	43.00 FL	*43.00 FL
7	1		*PANEL - FENDER, RH	Bent	401.00 FL	*401.00 FL
8	1		*INSULATOR - FENDER RH	Serviceable	27.00 FL	*- FL
9	1		*BEAM COMPLETE - FR BUMPER	Serviceable	544.00 FL	*- FL
10	1		*CARRIER ASSY - FRONT END MODULE	Bent	556.00 FL	*556.00 FL
11	1		*BRACKET ASSY - CARRIER MTG, RH	Serviceable	27.00 FL	*- FL
12	1		*EXTN - FR SIDE MEMBER OTR FR, RH	Serviceable	24.00 FL	*- FL
13	1		*REINF - FENDER APRON UPR, RH	Bent	62.00 FL	*62.00 FL
14	1		*PANEL ASSY - FNDR APRON, RH	Serviceable	263.00 FL	*- FL
15	1		*INSULATOR - DASH PANEL	Serviceable	114.00 FL	*- FL
16	1		*PAD - HOOD INSULATING	Deformed	119.00 FL	*119.00 FL
17	1		*LATCH ASSY - HOOD	Bent	101.00 FL	*101.00 FL
18	1		*GUARD ASSY - FRONT WHEEL, RH	Deformed	56.00 FL	*56.00 FL
19	1		*ORNAMENT - KIA NO.115	Necessary	32.00 FL	*32.00 FL
20	1		*COVER - FR BUMPER UPR	Distorted	476.00 FL	*476.00 FL
21	1		*SKID PLATE - FR BUMPER	Deformed	55.00 FL	*55.00 FL
22	1		*LIP ASSY - FRONT BUMPER	Cut	32.00 FL	*32.00 FL
23	1		*GRILLE ASSY - RADIATOR	Scratched	324.00 FL	*324.00 FL
24	1		*COVER - RADIATOR GRILLE UPR	Cracked	46.00 FL	*46.00 FL
25	1		*MOULDING - FRONT BUMPER A/INTAKE	Serviceable	61.00 FL	*- FL
26	1		*STRIP - FR BUMPER	Necessary	27.00 FL	*27.00 FL
27	1		*CAP - FRONT HOOK	Cut	5.00 FL	*5.00 FL
28	1		*COVER - FR BUMPER, LWR	Cracked	367.00 FL	*367.00 FL
29	1		*GRILLE - FRONT BUMPER	Deformed	96.00 FL	*96.00 FL
30	1		*ABSORBER - FRONT BUMPER ENERGY	Cracked	98.00 FL	*98.00 FL
31	1		*AIR DUCT - FR BUMPER, RH	Serviceable	38.00 FL	*- FL
32	1		*COVER - FR BUMPER FOG LAMP, RH	Cracked	64.00 FL	*64.00 FL
33	1		*LAMP ASSY - FRONT FOG, RH	Cracked	234.00 FL	*234.00 FL
34	1		*BRACKET - FR BUMPER SIDE, LH	Cracked	13.00 FL	*13.00 FL
35	1		*BRACKET - FR BUMPER SIDE, RH	Cracked	13.00 FL	*13.00 FL
36	1		*STIFFENER - FR BPR LWR	Serviceable	123.00 FL	*- FL
37	1		*GARNISH ASSY - FNDR SIDE, RH	Serviceable	45.00 FL	*- FL
38	1		*FRONT NUMBER PLATE WITH FRAME	Cracked	50.00 FS	*50.00 FS
39	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
40	3		*CLIP-MOUNTING	Necessary	9.00 FL	*9.00 FL
41	1		*COVER ASSY-COWL TOP	Cracked	166.00 FL	*166.00 FL
42	10		*CLIPS	Necessary	20.00 FL	*20.00 FL
43	1		*GUARD ASSY-FRONT WHEEL,LH	Cracked	56.00 FL	*56.00 FL
44	1		*MOULDING-WINDSHIELD GLASS	Necessary	52.00 FL	*52.00 FL
45	12		*PAD-WINDSHIELD GLASS	Necessary	24.00 FL	*24.00 FL
46	2		*STOPPER-RR WINDOW GLASS	Necessary	8.00 FL	*8.00 FL
47	4		*RETAINER	Necessary	4.00 FL	*4.00 FL
48	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	9,740.00	8,444.00
				- List Item Discount on L Items 20.00/20.00% (S\$)	1,928.00	1,674.80
				Total Parts (S\$)	7,812.00	6,769.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BUMPER, BONNET, SUPPORT, FRT RH FENDER, FRT RH WHEEL HOUSING & AFFECTED AREA TO REPAIR ON FRT RH BODY CHASSIS.	New	3,200.00	1,200.00
2	PAINT WORK ON FRT BUMPER, BONNET, FRT RH WHEEL HOUSING, FRT RH BODY CHASSIS & BOTH FRT FENDER.	New	2,100.00	1,400.00
3	TO REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR.	New	120.00	100.00
4	TO TOP UP AIRCON GAS.	New	80.00	80.00
5	TO REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR.	New	400.00	0.00
6	TO APPLY SEALANT ON AFFECTED AREA.	New	80.00	40.00
7	PERFORM RUST PREVENTION.	New	160.00	120.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
10	REPLACE FRONT END CARRIER,RH FRONT FENDER UPPER APRON,REPAIR LH FRONT FENDER AND ALL OTHER AFFECTED AREAS.	New	1,400.00	1,400.00
11	REMOVE & REINSTALL FRONT WINDSCREEN GLASS TO FACILITATE REPAIR, AND CONDUCT WATER LEAK TEST.	New	240.00	240.00
12	SUPPLY FRONT WINDSCREEN GLASS SEALANT	New	80.00	80.00
13	RESPRAY ON RH FRONT FENDER UPPER APRON	New	350.00	350.00
Gross Labour Cost (S\$)			8,360.00	5,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >