

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011535/T1VF3E2

Date: 12/11/2020

REFERENCE

Insured/Claimant:	CHNG SAY TIONG	Policy No:	1900001735	
Date of Loss:	21/10/2020	Nature of Claim:	OD	Claim No: 5796460752SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH448X		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHK1692
Reg. Date:	09/01/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AJH004442
Colour:	Red	Odometer:	24894 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,726.17	11,177.19	548.98	4.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,120.00	7,420.00	1,700.00	18.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,846.17	18,597.19	2,248.98	10.79
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	20,546.17	18,297.19	2,248.98	10.95
+ GST 7.00/7.00% (S\$)	1,438.23	1,280.80	157.43	10.95
Nett Amount (S\$)	21,984.40	19,577.99	2,406.41	10.95

INSPECTION

Date of Assignment: 22/10/2020
Date Inspected: 22/10/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE WITH FRAME	Missing	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*HEADLAMP ASSY, LH	Cracked	660.00 FL	*660.00 FL
4	1		*HEADLAMP ASSY, RH	Cracked	660.00 FL	*660.00 FL
5	1		*LAMP ASSY, FOG, FR LH	Not Necessary	303.00 FL	*- FL
6	1		*HORN	Not Necessary	79.00 FL	*- FL
7	1		*TANK, WINDSHIELD WASHER	Deformed	74.00 FL	*74.00 FL
8	1		*MOTOR, WINDSHIELD WASHER	Not Necessary	30.00 FL	*- FL
9	1		*CONDENSER ASSY, A/C REFRIGE	Bent	758.00 FL	*758.00 FL
10	1		*PIPE, A/C CONDENSER OUTLET	Bent	305.00 FL	*305.00 FL
11	1		*FACE, FR BUMPER	Deformed	703.00 FL	*703.00 FL
12	1		*COVER, HEADLAMP SUPT PANEL	Cracked	62.00 FL	*62.00 FL
13	1		*GRILLE, FR UNDER	Deformed	165.00 FL	*165.00 FL
14	1		*AIR DAM, SIDE, FR RH	Not Necessary	18.00 FL	*- FL
15	1		*AIR DAM, SIDE, FR LH	Not Necessary	18.00 FL	*- FL
16	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
17	1		*GARNISH, FR BUMPER, RH	Cut	127.00 FL	*127.00 FL
18	1		*BRACKET, FR BUMPER, RH	Deformed	13.00 FL	*13.00 FL
19	1		*BRACKET, FR BUMPER, LH	Deformed	13.00 FL	*13.00 FL
20	1		*GRILLE, RADIATOR	Necessary	554.00 FL	*554.00 FL
21	1		*HOOD	Bent	734.00 FL	*734.00 FL
22	1		*INSULATOR, HOOD	Deformed	177.00 FL	*177.00 FL
23	1		*HINGE, HOOD, LH	Bent	56.00 FL	*56.00 FL
24	1		*HINGE, HOOD, RH	Bent	56.00 FL	*56.00 FL
25	1		*LATCH, HOOD	Bent	69.00 FL	*69.00 FL
26	1		*FENDER, FR LH	Bent	497.00 FL	*497.00 FL
27	1		*FENDER, FR RH	Bent	497.00 FL	*497.00 FL
28	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	65.00 FL	*65.00 FL
29	1		*PANEL ASSY, FR END	Bent	1,055.00 FL	*1,055.00 FL
30	1		*COVER, ENG ROOM UNDER, FR	Not Necessary	99.00 FL	*- FL
31	1		*SHIELD, FR WHEELHOUSE, RH	Deformed	98.00 FL	*98.00 FL
32	1		*RADIATOR ASSY	Bent	967.00 FL	*967.00 FL
33	1		*PANEL, AIR GUIDE	Deformed	112.00 FL	*112.00 FL
34	1		*SHROUD, COOLING FAN	Cracked	130.00 FL	*130.00 FL
35	1		*MOTOR, COOLING FAN	Jammed	479.00 FL	*479.00 FL
36	1		*FAN, COOLING, LH	Deformed	77.00 FL	*77.00 FL
37	1		*ATTRAGE BODYKITS	Cracked	1,643.00 FS	*1,643.00 FS
38	1		*HOSE,A/C COMPR SUCTION	Bent	231.00 FL	*231.00 FL
39	1		*HOSE,A/C COMPR DISCHARGE	Bent	210.00 FL	*210.00 FL
40	1		*COVER FR BUMPER	Missing	13.00 FL	*13.00 FL
41	1		*PANEL,AIR GUIDE,RH	Cracked	11.00 FL	*11.00 FL
42	1		*PANEL,AIR GUIDE,LH	Cracked	11.00 FL	*11.00 FL
43	15		*CLIP,FR BUMPER	Necessary	60.00 FL	*60.00 FL
44	6		*CLIP,RR BUMPER	Necessary	18.00 FL	*18.00 FL
45	6		*RIVET,FR BUMPER	Necessary	30.00 FL	*30.00 FL
46	1		*MARK,THREE-DIA	Necessary	69.00 FL	*69.00 FL
47	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
48	1		*OIL COOLER ASSY,A/T	Dented	558.00 FL	*558.00 FL
49	1		*SENSOR,A/C CONDENSER	Cracked	94.00 FL	*94.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*COMPR & CLUTCH ASSY, A/C	Jammed	1,737.00 FL	*1,737.00 FL
51	1		*TANK ASSY, RADIATOR COND	Deformed	42.00 FL	*42.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					14,698.00	13,994.00
- List Item Discount on L Items 23.00/23.00% (S\$)					2,971.83	2,816.81
Total Parts (S\$)					11,726.17	11,177.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE FRT BUMPER, BONNET, SUPPORT, BOTH FRT FENDER & AFFECTED AREA REPAIR ON FRT RH BODY CHASSIS	New	3,150.00	2,250.00
2	PAINT WORK FRT BUMPER, BONNET, SUPPORT, FRT RH BODY CHASSIS, BODY KIT & BOTH FRT FENDER	New	2,450.00	2,100.00
3	TO REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR	New	450.00	0.00
5	TO TOP UP AIRCON GAS	New	80.00	80.00
6	PERFORM RUST PREVENTION	New	120.00	120.00
7	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	REPLACE ENGINE COMPONENTS PARTS	New	450.00	450.00
10	FLOOR PULLING	New	550.00	550.00
11	REPAIR LHF & RHF BODY CHASSIS	New	900.00	900.00
12	SPRAY PAINT LHF & RHF BODY CHASSIS	New	700.00	700.00
Gross Labour Cost (\$\$)			9,120.00	7,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >