



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2007863
INV Date 23/11/2020
Reference CS/SMO20011541/Kqf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SGB 5182G
Insured Veh. FBK 1832C
Claim No. CMTD2003099/RUC
Policy No.
Accident Date 22/10/2020
Inspection Date 26/10/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20011541/Kqf3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 23-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBK 1832C	Veh. Inspected	SGB 5182G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003099/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	26/10/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	MR053ZEC107108030	Colour	METALLIC SILVER
Odometer	206355	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	FIRENZA	5 mm
L/H Front Tyre	205/50 R16	FIRENZA	5 mm
R/H Rear Tyre	205/50 R16	FIRENZA	3 mm
L/H Rear Tyre	205/50 R16	FIRENZA	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/10/2020	Inspection Date	26/10/2020
Survey held at	H C AUTO PTE LTD 160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGB 5182G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN GLASS MOLDING	NECESSARY	80.00	80.00
1	BOOT LID	TO REPAIR SEE LABOUR	595.58	-
1	BOOT LID "TOYOTA" LOGO	NOT NECESSARY	52.50	-
1	BOOT LID "COROLLA" EMBLEM	NOT NECESSARY	42.35	-
1	BOOT LID "ALTIS" EMBLEM	NOT NECESSARY	44.17	-
1	BOOT LID "1.6" EMBLEM	NOT NECESSARY	32.81	-
1	BOOT LID "VVT-I" EMBLEM	NOT NECESSARY	32.81	-
1	O/S TAIL LAMP	BROKEN	360.98	360.98
1	O/S TAIL LAMP LOWER PANEL	BENT	76.86	76.86
1	REAR BUMPER	MISSING	459.75	459.75
2	REAR BUMPER SIDE RETAINER @\$66.76	CRACKED	133.52	133.52
2	REAR BUMPER BRACKET @\$82.81	TO REPAIR SEE LABOUR	165.62	-
2	REAR BUMPER STOPPER @\$29.60	SERVICEABLE	59.20	-
11	REAR BUMPER CLIP @\$3.50	NECESSARY	38.50	38.50
1	REAR BUMPER LOWER LIP	MISSING	985.50	985.50
1	REAR END PANEL	BENT	552.30	552.30
1	REAR END PANEL INNER GARNISH	SERVICEABLE	185.29	-
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	787.12	-
1	O/S REAR SHOCK ABSORBER	SERVICEABLE	114.88	-
1	O/S REAR HUP BEARING	NOT NECESSARY	462.00	-
1	REAR AXLE BEAM	SERVICEABLE	1,488.71	-
1	O/S REAR FENDER	BENT	1,125.80	1,125.80
1	O/S REAR FENDER INNER GARNISH	SERVICEABLE	168.20	-
1	O/S REAR FENDER OUTER GARNISH	DISTORTED	57.61	57.61
1	O/S REAR DOOR	TO REPAIR SEE LABOUR	1,052.10	-
1	O/S REAR DOOR PROTECTOR	SERVICEABLE	85.90	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	702.90	-

Report Ref No. CS/SMO20011541/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,485.74	-967.71
			7,457.22	2,903.11
1	REAR WEATHER STRIP (50%)(SN)	DISTORTED / DENTED	175.35	87.68
	LESS 25% DISCOUNT		-43.84	-
			131.51	87.68
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	60.00	30.00
1	REAR WINDSCREEN GLASS INNER GUM (SN)	NECESSARY	60.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	MISSING	350.00	200.00
1	REAR PANEL SEAL (SN)	NECESSARY	250.00	30.00
1	REAR NO PLATE (SN)	NOT NECESSARY	100.00	-
			820.00	300.00
	<u>LABOUR</u>			
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF BOOT LID,REAR BUMPER BRACKET,REAR EXHAUST BOX,O/S REAR DOOR AND REAR FLOOR PANEL.		1,800.00	1,100.00
	TO PUTTY AND SPRAY PAINTING.		1,500.00	800.00
	TO CHECK WIRING.		120.00	20.00
	TO RE-SEAL ANTI RUST.		180.00	60.00
	REMOVE AND REFIX REAR REVERSE SENSOR.		100.00	50.00
	REMOVE AND REFIX REAR EXHAUST BOX.		120.00	60.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		220.00	120.00
	REMOVE AND REFIX REAR CUSHION SEAT,CARPET,GARNISH & ETC.		350.00	120.00
	-		-	-
	-		-	-
	-		-	-
			4,390.00	2,330.00
GRAND TOTAL			12,798.73	5,620.79

Report Ref No. CS/SMO20011541/Kqf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	-----------------

Report Ref No. CS/SMO20011541/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.