

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20011545/KQF3Q2

**Date:** 09/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070106266

**Claimant**  
**Vehicle No :** GBK3406L **Insured Vehicle No :** SMT7593A

Date of Loss: 18/10/2020 Nature of Claim: TP Claim No: 8238512670SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBK3406L</b>		
Make & Model:	HONDA ACCORD, 1.6 (M)	Engine No:	1KD2867823
Reg. Date:	04/06/2020 (Man. Year: 2019)	Chassis No:	KDY2318040419
Colour:	Silver	Odometer:	26675 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8/8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8/8 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,793.33	1,801.55	991.78	35.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	870.00	530.00	37.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,193.33</b>	<b>2,671.55</b>	<b>1,521.78</b>	<b>36.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,193.33</b>	<b>2,100.00</b>	<b>2,093.33</b>	<b>49.92</b>

### INSPECTION

Date of Assignment: 23/10/2020

Date Inspected: 26/10/2020 Inspected At:

Massive Trading & Auto  
Blk 5038 #01-405, Ang Mo Kio  
Industrial Pk 2  
Singapore 569541

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S WHEEL GUARD	Bent	305.10 FL	*305.10 FL
2	1		*REAR N/S WHEEL GUARD BRACKET	Bent	255.10 FL	*255.10 FL
3	1		*REAR TOOL BOX	Bent	496.30 FL	*496.30 FL
4	2		*REAR TOOL BOX BRACKET	Distorted	310.20 FL	*310.20 FL
5	1		*REAR N/S WHEEL SPRING LEAF ASSY (LOCAL REPAIR)	Distorted	1,391.78 FS	*400.00 FS
6	1		*REAR N/S WHEEL SPRING LEAF BRACKET	Distorted	168.70 FL	*168.70 FL
7	1		*REAR N/S TYRE RIM	Dented	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,177.18</b>	<b>2,185.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	383.85	383.85

<b>Total Parts (\$)</b>	<b>2,793.33</b>	<b>1,801.55</b>
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING WELDING & CUTTING	New	500.00	350.00
2	TO PUTTY AND SPRAY PAINT ON REAR ACCIDENT PORTION	New	500.00	400.00
3	REMOVE/RENEW REAR N/S WHEEL SPRING LEAF ASSY	New	400.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,400.00</b>	<b>870.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**