

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 01 Dec 2020

Preliminary Advice

Vehicle No	: YQ342C	Accident Date	: 11/10/2020
Make	: MITSUBISHI CANTER	Policy No.	: Z20VC05005789
Assignment Date	: 22/10/2020	Excess	: S\$3,900.00
Date of Inspection	: 23/10/2020	Est. Duration of Repair	: 14
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,104.80	(ESTIMATE \$48,737.05 + SUPPLEMENTARY \$9,367.75)
Revised Amount	:S\$	44,133.35	
Check Items (Estimated)	:S\$	9,878.50	
Total	:S\$	54,011.85	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	8,793.00
Salvage Value	:S\$	
Margin for Repair	:S\$	66,207.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.
KINDLY APPROVE ON SUPPLEMENTARY.