

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI20011559/T1TF3Q2

**Date:** 12/11/2020

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant**

**Vehicle No :** GBD7131P

**Insured Vehicle No :** YM7197E

Date of Loss: 19/10/2020

Nature of Claim:

TP

Claim No: CDMCG20001508

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD7131P**

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR1SDEB (M) Engine No: 4P10B49855

Reg. Date: 27/03/2015 (Man. Year: 2015)

Chassis No: FEA01BA10018

Colour: White

Odometer: 233265 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 195R15(D)

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6/6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                   | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts                                   | 884.76            | 874.76            | 10.00             | 1.13          |
| Miscellaneous Items                     | 0.00              | 0.00              | 0.00              |               |
| Labour                                  | 900.00            | 600.00            | 300.00            | 33.33         |
| Paintwork Labour                        | 0.00              | 0.00              | 0.00              |               |
| Towing                                  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$)</b>      | <b>1,784.76</b>   | <b>1,474.76</b>   | <b>310.00</b>     | <b>17.37</b>  |
| <b>Approved Total (Overridden) (\$)</b> |                   | <b>1,150.00</b>   |                   |               |
| <b>(\$)</b>                             | 1,784.76          | 1,150.00          | 634.76            | 35.57         |
| <b>+ GST 7.00/7.00% (\$)</b>            | 124.93            | 80.50             | 44.43             | 35.56         |
| <b>Nett Amount (\$)</b>                 | <b>1,909.69</b>   | <b>1,230.50</b>   | <b>679.19</b>     | <b>35.57</b>  |

### INSPECTION

Date of Assignment: 22/10/2020

Date Inspected: 29/10/2020 Inspected At:

8 Tuas Ave 18

Singapore 638892

Repairer: Goldbell Engineering Pte Ltd

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 12 Nov 2020)   |  |
| <b>Parts:</b>        | N/A  | mitsubishi canter 3.0 D FEA01BR1SDEB (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBD7131P)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No.                      | Qty | Part No. | Particulars                | Condition | Repairer's | Amount        |
|--------------------------|-----|----------|----------------------------|-----------|------------|---------------|
| 1                        | 1   |          | *MIRROR,OUTSIDE RR VIEW    | Cracked   | 97.95 FS   | *97.95 FS     |
| 2                        | 1   |          | *STAY,RR VIEW MIRROR-RH    | Bent      | 435.13 FS  | *435.13 FS    |
| 3                        | 1   |          | *COVER,RR VIEW MIRROR STAY | Deformed  | 13.71 FS   | *13.71 FS     |
| 4                        | 1   |          | *COVER,FR BMPR CORNER,RH   | Missing   | 307.97 FS  | *307.97 FS    |
| 5                        | 1   |          | *SUNDRIES                  | Necessary | 30.00 FS   | *20.00 FS     |
| <b>Total Parts (S\$)</b> |     |          |                            |           |            | <b>884.76</b> |
|                          |     |          |                            |           |            | <b>874.76</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars  | Lab.Type | Repairer's    | Amount        |
|-------------------------------|--|----------|---------------|---------------|
| <u>Labour Items</u>           |  |          |               |               |
| 1                             | TO REMOVE AND REFIX DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN,ETC | New      | 900.00        | 600.00        |
| <b>Gross Labour Cost (\$)</b> |  |          | <b>900.00</b> | <b>600.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >