

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011567/ATF3E2

Date: 02/02/2021

REFERENCE

Insured/Claimant:	SINGHANIA MANAV	Policy No:	2070114801		
Date of Loss:	10/10/2020	Nature of Claim:	OD	Claim No:	4864412207SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU8190S	Engine No:	CZD895168
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF33L1111236
Reg. Date:	21/08/2020 (Man. Year: 2020)	Odometer:	530 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,387.00	2,362.00	9,025.00	79.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,022.00	1,522.00	2,500.00	62.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,409.00	3,884.00	11,525.00	74.79
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	15,009.00	3,484.00	11,525.00	76.79
+ GST 7.00/7.00% (S\$)	1,050.63	243.88	806.75	76.79
Nett Amount (S\$)	16,059.63	3,727.88	12,331.75	76.79

INSPECTION

Date of Assignment:	22/10/2020		
Date Inspected:	22/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,045.00 FS	*1,634.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	58.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - LH	Not Necessary	109.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	188.00 FS	*- FS
5	1		*FRONT SPOILER	Cut	379.00 FS	*303.20 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	151.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	38.00 FS	*- FS
8	1		*FRONT FENDER - LH	Not Necessary	1,271.00 FS	*- FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
10	1		*FRONT FENDER BRACE - LH	Not Necessary	87.00 FS	*- FS
11	1		*FRONT FENDER BRACKET - LH	Not Necessary	31.00 FS	*- FS
12	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	237.00 FS	*- FS
13	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	100.00 FS	*- FS
14	1		*HEADLIGHT MOUNTING - LH	Not Necessary	117.00 FS	*- FS
15	1		*LED HEADLIGHT - LH	Not Necessary	5,526.00 FS	*- FS
16	1		*LIFT CYLINDER	Not Necessary	208.00 FS	*- FS
17	2		*FRONT WHEEL COVER - LH / RH	Necessary	530.00 FS	*424.00 FS
18	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	11,387.00	2,362.00
-------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,500.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	New	1,650.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			4,022.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >