



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 3618G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	CUT	65.00	65.00
2	FORK INNER TUBES	SERVICEABLE	210.00	-
2	FORK OUTER TUBES	SERVICEABLE	220.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	145.00	-
1	FRONT BRACKET DISC	NOT NECESSARY	135.00	-
1	FRONT SPORT RIM	NOT NECESSARY	280.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	38.00	-
1	TOP COWLING	CRACKED	85.00	85.00
1	WINDSHIELD	CRACKED	32.00	32.00
1	LAMPSTAY	NOT NECESSARY	50.00	-
1	HEADLAMP	SERVICEABLE	70.00	-
2	SIDE MIRRORS	N/S BROKEN	70.00	35.00
2	HANDLE-BAR	N/S BENT	136.00	68.00
1	HAND GRIP (SET)	NECESSARY	35.00	35.00
2	HANDLE BAR ENDS	N/S SCRATCHED	36.00	18.00
1	CLUTCH LEVER	CRACKED	25.00	25.00
1	METER ASSY	NOT NECESSARY	480.00	-
1	FRONT FOOTREST-L/H	TORN	32.00	32.00
1	FRONT FOOTREST BRACKET-L/H	BENT	55.00	55.00
1	REAR FOOTREST	BROKEN	56.00	56.00
1	REAR CENTRE COWLING	NOT NECESSARY	35.00	-
1	MAIN STAND	NOT NECESSARY	70.00	-
1	SIDE STAND	NOT NECESSARY	58.00	-
2	SIDE BOARDS	TO REPAIR SEE LABOUR	96.00	-
	LESS 10% DISCOUNT		-251.40	-50.60
			2,262.60	455.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	FRT BENT	28.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-

Report Ref No. CS/TP20011568/Uvf3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN)	NOT NECESSARY	75.00	-
1	REAR BOX (SN)	CUT	150.00	150.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	90.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	100.00	-
			529.00	160.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE.		80.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.		350.00	200.00
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF SIDE BOARDS.		380.00	300.00
			890.00	535.00
GRAND TOTAL			3,681.60	1,150.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CS/TP20011568/Uvf3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.