



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

BLUWEL AUTOMOTIVE SERVICE PTE LTD

BLK 1 KAKI BUKIT AVE 6

#01-28/51/53/55(MAIN OFFICE)

SINGAPORE 417883

ON BEHALF OF KHOO CHENG BOON KENNETH

INV No. AC2007891

INV Date 24/11/2020

Reference CS/TP20011569/Uqf3n2

Code TP149



### PROFESSIONAL SERVICE FEE

Vehicle No. SBZ 106T

Insured Veh.

Claim No.

Policy No.

Accident Date 20/10/2020

Inspection Date 22/10/2020

Description	Total
Survey Inspection	767.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>767.00</b>
<b>GST (7%)</b>	<b>53.69</b>
<b>Grand Total</b>	<b>820.69</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP20011569/Uqf3n2		
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 24-11-2020		
ON BEHALF OF KHOO CHENG BOON KENNETH		Code : TP149		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	Veh. Inspected		SBZ 106T	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		22/10/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI TT COUPE (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	TRUZZZ8J6C1021079	Colour	BLACK	
Odometer	113700	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/45 R17	MICHELIN	6 mm	
L/H Front Tyre	245/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	245/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	245/45 R17	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/10/2020	Inspection Date	22/10/2020	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBZ 106T**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAILGATE	BADLY DENTED	3,910.00	3,910.00
1	TAILGATE REAR LOGO	NECESSARY	120.00	120.00
1	TAILGATE "TT" EMBLEM	NECESSARY	92.00	92.00
1	TAILGATE "TFSI" EMBLEM	NECESSARY	95.00	95.00
2	TAILGATE INNER DAMPERS @\$299.00	DAMAGED / TWISTED	598.00	598.00
1	TAILGATE INNER LOCK	SHORTED	212.00	212.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	299.00	-
1	REAR WINDSCREEN	NOT NECESSARY	1,428.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	165.00	165.00
1	REAR BUMPER	DENTED	3,102.00	3,102.00
1	REAR BUMPER DIFFUSER	DEFORMED	674.00	674.00
1	REAR BUMPER LAMP	CRACKED	220.00	220.00
2	REAR BUMPER PDC SENSORS @\$198.00	SHORTED	396.00	396.00
1	REAR BUMPER SPONGE	TORN	238.00	238.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	750.00	-
2	REAR BUMPER SIDE RETAINERS @\$95.00	NOT NECESSARY	190.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	TAILLAMPS @\$745.00	CRACKED	1,490.00	1,490.00
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	456.00	-
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	1,320.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,550.00	-
1	REAR EXHAUST HEAT SHIELD	BENT	255.00	255.00
	LESS 5% DISCOUNT		-	-580.85
			17,610.00	11,036.15
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR LICENCE PLATE (SN)	BENT	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00

Report Ref No. CS/TP20011569/Uqf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			150.00	80.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	100.00
	TO TRANSFER TAILGATE COMPONENTS.		100.00	80.00
	TO SPRAY RUST PROOFING.		100.00	50.00
	TO RESET & REPROGRAMME SYSTEM.		100.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT,REAR END PANEL OUTER,REAR END PANEL INNER AND REAR EXHAUST.		900.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	1,000.00
			2,600.00	2,050.00
<b>GRAND TOTAL</b>			<b>20,360.00</b>	<b>13,166.15</b>
<b>RECOMMENDED COST OF REPAIR SUM</b>				<b>11,800.00</b>

Report Ref No. CS/TP20011569/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.