

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20011570/R1BA3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SBS3501C	Insured Vehicle No :	SHC3704Y
Date of Loss:	20/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100359

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS3501C	Engine No:	D9194553
Make & Model:	VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)	Chassis No:	YV3S4P928GA174219
Reg. Date:	01/12/2015 (Man. Year: 2015)	Odometer:	340829 km
Colour:	Green		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8/8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,541.10	6,629.04	912.06	12.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,280.00	3,400.00	3,880.00	53.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,821.10	10,029.04	4,792.06	32.33
+ GST 7.00/7.00% (S\$)	1,037.48	702.03	335.45	32.33
Nett Amount (S\$)	15,858.58	10,731.07	5,127.51	32.33
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	26/10/2020		
Date Inspected:	26/10/2020	Inspected At:	Boxfresh Pte Ltd (HQ) 154 GUL CIRCLE Singapore 629611
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Mar 2021)	
Parts:	N/A	VOLVO B9TL 9.4 D AUTO TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3501C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NS #3 PANEL	Bent	790.37 F	*790.37 F
2	1		*NS #4 PANEL	Serviceable	875.10 F	*- F
3	1		*MID BODY PILLAR	Bent	1,571.43 F	*1,571.43 F
4	1		*MID BODY PILLAR	Bent	972.48 F	*972.48 F
5	1		*ADH SIKI 265 600 MLS (7 PCS)	Necessary	436.40 F	*436.40 F
6	1		*SIKA 552 WHITE 600MLO SAUSAGE (10 PCS)	Necessary	629.85 F	*629.85 F
7	1		*PILLAR TRIM INFILL	Bent	139.41 F	*139.41 F
8	1		*HUCK MAGNA MONOBOT (150PCS)	Necessary	154.28 F	*154.28 F
9	1		*ALLOY CAPPLING FOR LD	Necessary	32.67 F	*32.67 F
10	1		*ENTRANCE DOOR PILLAR CAPPING	Necessary	90.00 F	*90.00 F
11	1		*VERTICAL WINDOW CAPPING RAL 7035 (2 PCS)	Necessary	275.03 F	*275.03 F
12	1		*PLASTIC CAPPING	Necessary	22.70 F	*22.70 F
13	2		*CLADDING CAPPLING ENDCAP LHS	Serviceable	36.96 F	*- F
14	1		*PILLAR REPAIR KIT (FOR 01G00163)	Necessary	722.74 F	*722.74 F
15	1		*PILLAR REPAIR KIT (FOR G01-00097)	Necessary	791.68 F	*791.68 F
					Total Parts (\$\$)	7,541.10
						6,629.04

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY REPLACEMENT NEW PARTS .RESPRAY OF DAMAGED PARTS MADE GOOD	New	1,280.00	400.00
2	LABOUR CHARGES:STRIPPING OF ALL DAMAGED PARTS ,REFIT OF ALL REPLACE PARTS,DISMANTLE OF GLASS PANEL FOR REPAIR ,RE- INSTALL OF ALL NEW PARTS REPLACED,INSTALL NEW DOOR AND AL WINDOW CAPPING,INSTALL NEW BODY PANELS,REFIT LOWER SIDEGLASSES ,REPAIRING OF DAMAGED PILLARS	New	6,000.00	3,000.00
Gross Labour Cost (S\$)			7,280.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >