

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6860C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BROKEN	499.90	499.90
1	FRONT BUMPER LWR REINFORCEMENT BRACKET LH	NOT NECESSARY	165.00	-
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FOG LAMP LH	NOT NECESSARY	920.00	-
1	HEADLAMP LH	NOT NECESSARY	3,455.00	-
1	FRONT FENDER - LH	DENTED	945.30	945.30
1	FRONT FENDER SHIELD LH	NOT NECESSARY	198.50	-
1	FRONT FENDER SHIELD CLIP	NOT NECESSARY	38.00	-
1	FRONT WHEEL RIM LH	NOT NECESSARY	1,570.55	-
	LESS 25% DISCOUNT		-1,953.56	-361.30
			5,860.69	1,083.90
	<u>LABOUR</u>			
	PANEL BEATING.		650.00	320.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.		100.00	30.00
	WHEEL ALIGNMENT.		60.00	60.00
			1,310.00	810.00
	GRAND TOTAL		7,170.69	1,893.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,500.00

Report Ref No. NS/INC20011572/Etf3e2


CHEN TSUE YEE

Automotive Assessor


K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.