

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011576/KPS3Q2

Date: 10/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800024053
Claimant Vehicle No :	GBJ9986U	Insured Vehicle No :	SLZ211D
Date of Loss:	22/10/2020	Nature of Claim:	TP
		Claim No:	0337722293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ9986U		
Make & Model:	SSANGYONG ACTYON SPORTS, 2.2 D 6AT 2WD ABS E6 (A)	Engine No:	67296022615228
Reg. Date:	07/11/2019 (Man. Year: 2018)	Chassis No:	KPADA1EESJP329529
Colour:	Metallic Silver	Odometer:	15578 km
Engine Capacity:	2157 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/75 R16	Rear Tyre Size:	225/75 R16
Front Left Side:	Nexen 9 mm	Rear Left Side:	Nexen 9 mm
Front Right Side:	Nexen 9 mm	Rear Right Side:	Nexen 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,378.28	1,974.30	1,403.98	41.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	870.00	970.00	52.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,218.28	2,844.30	2,373.98	45.49
+ GST 7.00/7.00% (S\$)	365.28	199.10	166.18	45.49
Nett Amount (S\$)	5,583.56	3,043.40	2,540.16	45.49
+ Loss of Use (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,525.40		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment:	26/10/2020	
Date Inspected:	16/11/2020	Inspected At: MBM Wheelpower Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-15, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,280.00 FL	*820.00 FL
2	1		*REAR BUMPER LOWER COVER	No such part	420.00 FL	*- FL
3	1		*REAR BUMPER CENTER CARRIER	Bent	490.00 FL	*460.00 FL
4	1		*REAR BUMPER LH REFLECTOR	Cracked	72.00 FL	*72.00 FL
5	10		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
6	1		*REAR BUMPER LH SIDE RETAINER	Distorted	166.00 FL	*118.00 FL
7	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	166.00 FL	*- FL
8	1		*TAIL LAMP LH	Cracked	691.20 FL	*515.00 FL
9	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
10	1		*TRUNK LID SSANGYONG EMBLEM	Necessary	130.00 FL	*65.00 FL
11	1		*TRUNK LID SPORTS EMBLEM	Necessary	134.00 FL	*67.00 FL
12	1		*70KM/H STICKER	Necessary	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,739.20	2,192.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	360.92	217.70
Total Parts (\$\$)	3,378.28	1,974.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	800.00	400.00
2	TO APPLY ANTI RUST COATING	New	150.00	0.00
3	TO REMOVE ,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
4	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	50.00
5	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	400.00
Gross Labour Cost (S\$)			1,840.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >