

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011577/T1PA3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2070102148	
Claimant Vehicle No : SLA8305X	Insured Vehicle No : SGT238H	
Date of Loss: 22/10/2020	Nature of Claim: TP	Claim No: 3225795913SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA8305X		
Make & Model: VOLKSWAGEN GOLF, 1.4 TSI (A)	Engine No: CZC405672	
Reg. Date: 18/03/2016 (Man. Year: 2015)	Chassis No: WVVZZZAUZGW040293	
Colour: White	Odometer: 77698 km	
Engine Capacity: 1395 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17	Rear Tyre Size: 225/45 R17	
Front Left Side: Pirelli 6 mm	Rear Left Side: Pirelli 6 mm	
Front Right Side: Pirelli 6 mm	Rear Right Side: Pirelli 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,216.65	4,882.30	6,334.35	56.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,470.00	1,290.00	46.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,976.65	6,352.30	7,624.35	54.55
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	13,976.65	5,100.00	8,876.65	63.51
+ GST 7.00/7.00% (S\$)	978.37	357.00	621.37	63.51
Nett Amount (S\$)	14,955.02	5,457.00	9,498.02	63.51
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,093.45		
Global Sum Settlement (S\$)		6,090.00		

INSPECTION

Date of Assignment: 26/10/2020		
Date Inspected: 26/10/2020	Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair: 5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,267.86 FL	*1,012.00 FL
2	1		*REAR BUMPER RETAINER LH	Necessary	57.78 FL	*57.78 FL
3	1		*REAR BUMPER REFLECTOR LH	Not Necessary	99.26 FL	*- FL
4	1		*TAILLAMP LH	Cracked	414.70 FL	*248.00 FL
5	1		*REAR FENDER LH	Buckled	1,877.78 FL	*1,429.00 FL
6	1		*REAR FENDER INNER SHIELD LH	Deformed	257.52 FL	*214.60 FL
7	1		*REAR LH LOWER ARM	Bent	442.90 FL	*350.00 FL
8	1		*REAR LH UPPER ARM	Not Necessary	442.24 FL	*- FL
9	1		*REAR LH KNUCKLE ARM	Bent	918.90 FL	*750.00 FL
10	1		*REAR LH KNUCKLE ARM BEARING	Bent	575.70 FL	*400.10 FL
11	1		*REAR LH SHOCK ABSORBER	Bent	422.62 FL	*263.30 FL
12	1		*REAR LH TRAILINK ARM	Not Necessary	538.26 FL	*- FL
13	1		*REAR LH CONTROL ARM	Not Necessary	324.22 FL	*- FL
14	1		*REAR LH DOOR PANEL	Repair	2,187.30 FL	*- FL
15	1		*REAR LH DOOR WEATHERSTRIP	Not Necessary	147.02 FL	*- FL
16	1		*RIM	Cut	1,000.00 FS	*600.00 FS
17	1		*RIM LOGO	Not Necessary	120.00 FS	*- FS
18	1		*TYRE	Not Necessary	600.00 FS	*- FS
19	1		*BOT BRAKE FUILD	Not Necessary	60.00 FS	*- FS
20	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
21	1		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	30.00 FS	*- FS
22	1		*SET REAR REVERSE SENSOR	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,214.06	5,354.78
- List Item Discount on L Items 10.00/10.00% (S\$)	997.41	472.48
Total Parts (S\$)	11,216.65	4,882.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	New	150.00	80.00
3	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	New	200.00	100.00
4	REMOVE ,REPLACE AND REFIT REVERSE SENSOR	New	200.00	30.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	600.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (S\$)			2,760.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >