



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20011579/AUvf3q2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 09-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 1035R	Veh. Inspected	SLT 6548A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003084/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	26/10/2020

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO FORTE KOUP	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFW611MA5202943	Colour	RED
Odometer	176637	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	NEXEN	6 mm
L/H Front Tyre	215/45 R17	NEXEN	6 mm
R/H Rear Tyre	215/45 R17	NEXEN	6 mm
L/H Rear Tyre	215/45 R17	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/10/2020	Inspection Date	28/10/2020
Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**