

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20011580/ERA3Q2

Date:

27/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900244624

Claimant Vehicle No : SHC2559G**Insured Vehicle No :**

SKS390T

Date of Loss: 22/10/2020

Nature of Claim:

TP

Claim No:

0150136448SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC2559G**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2B82410

Reg. Date: 06/12/2018 (Man. Year: 2018)

Chassis No: JTDKB3FU803077518

Colour: Blue

Odometer: 324192 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,106.25	2,478.72	627.53	20.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,890.00	490.00	20.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,486.25	4,368.72	1,117.53	20.37
+ GST 7.00/7.00% (S\$)	384.04	305.81	78.23	20.37

Nett Amount (S\$)	5,870.29	4,674.53	1,195.76	20.37
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$126.47/day) (S\$)		505.88		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,382.41		

INSPECTION

Date of Assignment: 22/10/2020

Date Inspected: 22/10/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: Jaslin Kok Chin Yi**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Dented	1,264.00 FL	*1,264.00 FL
2	1		*REAR DOOR -RH	Dented	1,258.30 FL	*1,258.30 FL
3	1		*REAR FENDER -RH	Repair	836.70 FL	*- FL
4	1		*ROCKER PANEL GARNISH RH	Broken	576.00 FL	*576.00 FL
5	1		*FRONT DOOR COMFORTDELGRO STICKER -RH	Necessary	75.00 FS	*75.00 FS
6	1		*REAR DOOR APP STICKER -RH	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,090.00	3,253.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	983.75	774.58
Total Parts (\$\$)	3,106.25	2,478.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	980.00	960.00
2	SPRAY PAINTING CHARGE	New	1,000.00	800.00
3	TUFF KOTE	New	100.00	30.00
4	TRANSFER OF DOOR	New	300.00	100.00
Gross Labour Cost (\$)			2,380.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >