

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011584/KCD3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00092252000
Claimant Vehicle No :	SLK8075G	Insured Vehicle No :	SMM9494B
Date of Loss:	20/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203993/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8075G	Engine No:	L15B5000944
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81100781
Reg. Date:	26/01/2017 (Man. Year: 2016)	Odometer:	127679 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,404.48	3,247.24	1,157.24	26.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	690.00	420.00	270.00	39.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,094.48	3,667.24	1,427.24	28.02
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	5,094.48	2,900.00	2,194.48	43.08
+ GST 7.00/7.00% (S\$)	356.61	203.00	153.61	43.08
Nett Amount (S\$)	5,451.09	3,103.00	2,348.09	43.08

INSPECTION

Date of Assignment: 29/10/2020

Date Inspected: 26/10/2020 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,
#01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Mar 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK8075G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,152.00 FL	*1,020.20 FL
2	12		*FRONT BUMPER CLIPS	Necessary	66.00 FL	*66.00 FL
3	1		*FRONT BUMPER CORNER RETAINER LH	Distorted	21.00 FL	*21.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	297.50 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP LH	Mtg Cracked	347.00 FL	*347.00 FL
6	1		*FRONT BUMPER FOG LAMP CHROME GARNISH	Scratched	95.20 FL	*95.20 FL
7	1		*FRONT BUMPER CENTER AIR GRILLE SIDE COVER LH (TOP)	Scratched	33.20 FL	*33.20 FL
8	1		*FRONT BUMPER CENTER AIR GRILLE SIDE COVER LH (BOTTOM)	Scratched	95.20 FL	*95.20 FL
9	1		*AIR CLEANER RESONATOR	Serviceable	89.50 FL	*- FL
10	1		*AIR CLEANER RESONATOR HOSE	Serviceable	50.10 FL	*- FL
11	1		*HEADLAMP LH (LED)	Cut	2,250.40 FL	*2,250.40 FL
12	1		*HEADLAMP LOWET EXT ARM	Cracked	146.00 FL	*62.10 FL
13	1		*FRONT BUMPER INNER ELECTROMASNETIC PARKING SENSOR	No such part	450.00 FS	*- FS
14	1		*FRONT NUMBER PLATE WRITTERS (CHROME)	Necessary	120.00 FS	*35.00 FS
15	1		*HEADLAMP LOWER GARNISH	Necessary	120.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,333.10	4,045.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	928.62	798.06
Total Parts (\$\$)	4,404.48	3,247.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT FRONT ELECTRICAL CHECK, FOCUS HEADLAMP	New	30.00	20.00
2	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	0.00
3	LABOUR CHARGE-PANEL BEATING, REPAIRING OF BUMPER BEAM, LOWER PANEL AND PART REPLACEMENT	New	300.00	200.00
4	TO RESPRAY AFFECTED AREAS	New	280.00	200.00
Gross Labour Cost (\$\$)			690.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >