

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20011596/EGA3Q2

**Date:** 15/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800056880

**Claimant Vehicle No :** SHB6622K **Insured Vehicle No :** SLZ3928A

Date of Loss: 24/10/2020 Nature of Claim: TP Claim No: 2938005627SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB6622K</b>		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU404283
Reg. Date:	16/01/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU188722
Colour:	Blue	Odometer:	46114 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,649.80	715.00	1,934.80	73.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	520.00	710.00	57.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>3,879.80</b>	<b>1,235.00</b>	<b>2,644.80</b>	<b>68.17</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	271.59	86.45	185.14	68.17
<b>Nett Amount (\$\$)</b>	<b>4,151.39</b>	<b>1,321.45</b>	<b>2,829.94</b>	<b>68.17</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (\$\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$125.19/day) (\$\$)</b>		375.57		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,849.02</b>		

### INSPECTION

Date of Assignment: 26/10/2020

Date Inspected: 26/10/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	2		*REAR BUMPER SIDE RETAINER RH/LH	Not Necessary	111.60 FL	*- FL
3	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	276.20 FL	*- FL
6	1		*REAR BUMPER LOWER MOULDING	Cut	155.00 FL	*155.00 FL
7	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
8	1		*REAR BUMPER CENTRE MOULDING	Cut	451.25 FL	*451.25 FL
9	2		*REAR BUMPER REFLECTOR RH/LH	Not Necessary	63.80 FL	*- FL
10	1		*REAR FLOOR UNDER	Not Necessary	225.00 FL	*- FL
11	1		*SMART KEY ANTENNA	Not Necessary	665.40 FL	*- FL
12	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	*- FL
13	1		*REAR NUMBER PLATE /W HOLDER	Broken	50.00 FS	*50.00 FS
14	1		*REAR REVERSE SENSOR	Broken	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,254.75</b>	<b>836.25</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	604.95	121.25
<b>Total Parts (\$)</b>	<b>2,649.80</b>	<b>715.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	650.00	320.00
2	SPRAY PAINTING CHARGE	New	400.00	200.00
3	CHECK WIRING	New	60.00	0.00
4	TUFF KOTE	New	60.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,230.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**