Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20011599/ABA3Q2

Date: 04/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070100630

Claimant
Vehicle No: SMM7948Y

Insured Vehicle No: SJZ5156X

Date of Loss: 22/10/2020 Nature of Claim: TP Claim No: 0130787474SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM7948Y

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHT7955

Reg. Date: 15/07/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH002237

Colour: White Odometer: 17717 km

Engine Capacity: 1193 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,281.55	730.80	4,550.75	86.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	660.00	1,880.00	74.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,821.55	1,390.80	6,430.75	82.22
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	7,821.55	1,100.00	6,721.55	85.94
+ Car Rental (2.0 x S\$1	240.00			
+ Doc/Search Fee (S\$)		2.00		
Ne	tt Liability (S\$)	1,342.00		

INSPECTION

Date of Assignment: 23/10/2020

Date Inspected: 23/10/2020 Inspected At: SM Automotive (HQ)

756 JURONG WEST STREET 74,

#12-60

Singapore 640756

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

		Particulars	Condition	Repairer's	Amount
1		*FRONT R/H HEAD LAMP	Not Necessary	380.75 F	*-FL
1		*FRONT R/H HEAD LAMP LOWER BRACKET	Not Necessary	33.00 F	*- FL
1		*FRONT R/H FENDER	Dented	371.30 F	*371.30 FL
1		*FRONT R/H FENDER ECO LOGO	Necessary	22.70 F	*22.70 FL
1		*FRONT R/H FENDER COWLING	Not Necessary	85.60 F	*- FL
8		*FRONT R/H FENDER COWLING CLIP	Not Necessary	52.00 F	*- FL
1		*FRONT R/H FENDER SIGNAL LAMP	Not Necessary	39.70 F	*- FL
1		*FRONT BUMPER	Not Necessary	661.50 F	*- FL
8		*FRONT BUMPER CLIP	Not Necessary	52.00 F	*- FL
1		*FRONT R/H BUMPER SIDE RETAINER	Not Necessary	25.10 F	*- FL
1		*FRONT BUMPER LOWER LID	Not Necessary	950.00 FS	*- FS
1		*FRONT R/H BUMPER FOG LAMP	Not Necessary	311.30 F	*- FL
1		*FRONT R/H BUMPER FOG LAMP COVER ASSY	Not Necessary	105.60 F	*- FL
1		*FRONT R/H TYRE	Not Necessary	350.00 F	*- FL
1		*FRONT R/H RIM	Not Necessary	786.00 F	*- FL
1		*FRONT R/H KNUCKLE ARM	Not Necessary	329.00 F	*- FL
1		*FRONT R/H KNUCKLE ARM BEARING	Damaged	114.00 F	*114.00 FL
1		*FRONT R/H LOWER ARM	Bent	304.00 F	*304.00 FL
1		*FRONT R/H SHOCK ABSORBER	Not Necessary	308.00 F	*- FL
anchise	part. S=Spc	Nett. L=ListItemDisc.			
			· · /	•	812.00
- List Item Discount on L Items 0.00/10.00% (S\$)				0.00	81.20
			Total Parts (S\$)	5,281.55	730.80
	1 1 1 1 1 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 8 1 1 1 1 1 1 1 1 1 1 1 1	1 *FRONT R/H HEAD LAMP LOWER BRACKET 1 *FRONT R/H FENDER 1 *FRONT R/H FENDER ECO LOGO 1 *FRONT R/H FENDER COWLING 8 *FRONT R/H FENDER COWLING CLIP 1 *FRONT R/H FENDER SIGNAL LAMP 1 *FRONT BUMPER 8 *FRONT BUMPER CLIP 1 *FRONT R/H BUMPER SIDE RETAINER 1 *FRONT BUMPER LOWER LID 1 *FRONT R/H BUMPER FOG LAMP 1 *FRONT R/H BUMPER FOG LAMP 1 *FRONT R/H TYRE 1 *FRONT R/H RIM 1 *FRONT R/H KNUCKLE ARM 1 *FRONT R/H KNUCKLE ARM 1 *FRONT R/H LOWER ARM 1 *FRONT R/H LOWER ARM 1 *FRONT R/H SHOCK ABSORBER Inchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT R/H HEAD LAMP LOWER BRACKET Not Necessary 1 *FRONT R/H FENDER 1 *FRONT R/H FENDER ECO LOGO Necessary 1 *FRONT R/H FENDER COWLING Not Necessary 8 *FRONT R/H FENDER COWLING CLIP Not Necessary 1 *FRONT R/H FENDER SIGNAL LAMP Not Necessary 1 *FRONT BUMPER Not Necessary 1 *FRONT BUMPER CLIP Not Necessary 1 *FRONT R/H BUMPER SIDE RETAINER Not Necessary 1 *FRONT R/H BUMPER SIDE RETAINER Not Necessary 1 *FRONT BUMPER LOWER LID Not Necessary 1 *FRONT R/H BUMPER FOG LAMP Not Necessary 1 *FRONT R/H BUMPER FOG LAMP COVER ASSY Not Necessary 1 *FRONT R/H TYRE Not Necessary 1 *FRONT R/H RIM Not Necessary 1 *FRONT R/H KNUCKLE ARM Not Necessary 1 *FRONT R/H KNUCKLE ARM DAMP NOT Necessary 1 *FRONT R/H KNUCKLE ARM BEARING DAMAGED 1 *FRONT R/H KNUCKLE ARM BEARING DAMAGED 1 *FRONT R/H LOWER ARM BEARING DAMAGED 1 *FRONT R/H SHOCK ABSORBER NOT NOT Necessary Inchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$)	*FRONT R/H HEAD LAMP LOWER BRACKET Not Necessary 33.00 F *FRONT R/H FENDER Dented 371.30 F *FRONT R/H FENDER ECO LOGO Necessary 22.70 F *FRONT R/H FENDER COWLING Not Necessary 85.60 F *FRONT R/H FENDER COWLING Not Necessary 52.00 F *FRONT R/H FENDER SIGNAL LAMP Not Necessary 39.70 F *FRONT BUMPER Not Necessary 661.50 F *FRONT BUMPER CLIP Not Necessary 52.00 F *FRONT R/H BUMPER SIDE RETAINER Not Necessary 25.10 F *FRONT BUMPER LOWER LID Not Necessary 950.00 F S *FRONT R/H BUMPER FOG LAMP Not Necessary 311.30 F *FRONT R/H BUMPER FOG LAMP Not Necessary 105.60 F *FRONT R/H TYRE Not Necessary 350.00 F *FRONT R/H RIM Not Necessary 329.00 F *FRONT R/H KNUCKLE ARM Not Necessary 329.00 F *FRONT R/H KNUCKLE ARM Bent 304.00 F *FRONT R/H SHOCK ABSORBER Not Necessary 308.00 F *FRONT R/H SHOCK ABSORBER NOT NECESSARY NOT NEC

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & REFIT UNDERCARRIAGE PARTS	New	280.00	120.00
2	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
3	TO CHECK WIRING	New	100.00	0.00
4	TUFF KOTE	New	150.00	0.00
5	PANEL BEATING	New	800.00	200.00
6	SPRAY PAINTING	New	1,000.00	200.00
7	TOWING FEES	New	60.00	60.00
	Gross L	abour Cost (S\$)	2,540.00	660.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.