

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20011605/DES3Q2
Date: 05/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	SLZ3940M	Insured Vehicle No :	SHD2229D
Date of Loss:	26/10/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002211

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3940M		
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Engine No:	2ZR0A83374
Reg. Date:	30/04/2018 (Man. Year: 2018)	Chassis No:	ZVW400028058
Colour:	Blue	Odometer:	135960 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,003.66	3,460.61	11,543.05	76.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,550.00	1,530.00	5,020.00	76.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,553.66	4,990.61	16,563.05	76.85
Approved Total (Overridden) (S\$)		4,000.00		

(S\$)	21,553.66	4,000.00	17,553.66	81.44
+ GST 7.00/7.00% (S\$)	1,508.76	280.00	1,228.76	81.44
Nett Amount (S\$)	23,062.42	4,280.00	18,782.42	81.44
+ Car Rental (8.0 x S\$130.00/day) (S\$)		1,040.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,356.45		

INSPECTION

Date of Assignment: 26/10/2020

Date Inspected: 27/10/2020

Estimated Period of Repair: 5.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2021)
Parts:	144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ3940M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,659.20 FL	*929.00 FL
2	1		*TAILGATE INNER TRIM BOARD	Not Necessary	525.50 FL	*- FL
3	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	20.00 FL	*- FL
4	1		*TAILGATE CENTER MOULDING	Not Necessary	495.79 FL	*- FL
5	1		*SET TAILGATE CENTER MOULDING CLIPS	Not Necessary	20.00 FL	*- FL
6	1		*TAILGATE TOYOTA LOGO	Necessary	72.50 FL	*72.50 FL
7	1		*TAILGATE PRIUS PLUS EMBLEM	Necessary	65.90 FL	*65.90 FL
8	1		*TAILGATE HYBRID SYNERGY EMBLEM	Necessary	79.62 FL	*79.62 FL
9	1		*TAILGATE SWITCH	Not Necessary	352.90 FL	*- FL
10	1		*TAILGATE LOCK	Damaged	461.60 FL	*360.00 FL
11	1		*TAILGATE WEATHERSTRIP	Necessary	399.82 FL	*218.00 FL
12	1		*TAIL LAMP LH/RH	N/S Not Necessary / O/SCracked	1,203.80 FL	*410.00 FL
13	2		*TAIL LAMP PANEL LH/RH	Not Necessary	679.60 FL	*- FL
14	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	418.80 FL	*- FL
15	1		*REAR BUMPER	Distorted	1,030.59 FL	*524.00 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
17	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	288.84 FL	*- FL
18	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	218.66 FL	*- FL
19	1		*REAR END PANEL	Dented	880.80 FL	*630.00 FL
20	1		*REAR END PANEL TOP GARNISH	Mtg Deformed	332.40 FL	*255.80 FL
21	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FL	*20.00 FL
22	1		*SPARE WHEEL PANEL	Not Necessary	1,219.48 FL	*- FL
23	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	1,397.48 FL	*- FL
24	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	412.99 FL	*- FL
25	1		*REAR FENDER LH /RH	Not Necessary	3,695.72 FL	*- FL
26	1		*REAR FENDER INNER TRIM LH/RH	O/S Cracked / N/SNot Necessary	1,764.84 FL	*656.00 FL
27	1		*REAR TOOL BOX	Serviceable	601.39 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
29	1		*REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
30	1		*TAIL LAMP SEALANT	Not Necessary	60.00 FS	*- FS
31	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
33	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,588.22	4,520.82
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,584.56	1,060.21
Total Parts (\$\$)	15,003.66	3,460.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	60.00
6	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
7	TO RNR TAILGATE WINDSCREEN TO ASSIST WORK LOAD	New	300.00	120.00
8	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	400.00	0.00
9	TO RNR REVERSE SENSOR & REVERSE CAMERA	New	300.00	0.00
10	TO CHEKC & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTING	New	300.00	0.00
Gross Labour Cost (S\$)			6,550.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >