



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 5666D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	CUT	175.00	155.00
1	FRONT FORK ASSY	TO REPAIR SEE LABOUR	1,900.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	260.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	385.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	68.00	-
1	FRONT WHEEL RIM	DENTED / BENT	850.00	820.00
1	HANDLE-BAR	BENT	155.00	155.00
2	HANDLE-BAR ENDS	O/S CUT	90.00	45.00
1	SET HAND GRIPS	TORN	80.00	80.00
1	BRAKE LEVER	CUT	65.00	65.00
1	SET FRONT SIGNALS	BROKEN	230.00	200.00
1	FRONT FOOTREST-R/H	CUT	75.00	75.00
1	FRONT FOOTREST BRACKET- R/H	NOT NECESSARY	245.00	-
1	BRAKE PEDAL	CUT	95.00	95.00
1	GEAR PEDAL	BENT	95.00	95.00
1	REAR FOOTREST - R/H	CUT	70.00	70.00
1	REAR FOOTREST BRACKET - R/H	CUT	80.00	80.00
1	RADIATOR SIDE COVER - R/H	CUT	158.00	158.00
1	FRONT FOOTREST BRACKET - L/H	NOT NECESSARY	65.00	-
1	TANK SIDE COVER - R/H	CUT	150.00	150.00
1	FRONT LOWER SIDE COVER - R/H	NOT NECESSARY	150.00	-
1	SET MIRROR	CUT	190.00	190.00
1	THROTTLE CABLE	CUT	120.00	120.00
1	TOP BRAKE PUMP ASSY	CUT	180.00	180.00
	LESS 10% DISCOUNT		-593.10	-273.30
			5,337.90	2,459.70
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	FRONT BENT	28.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-

Report Ref No. CS/UOI20011606/Uqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN)	NOT NECESSARY	95.00	-
			209.00	10.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		80.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	FRONT FORK REPAIR.		200.00	80.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY.		400.00	280.00
			760.00	395.00
GRAND TOTAL			6,306.90	2,864.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS/UOI20011606/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.