

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





881.00

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3111M

RECOMMENDED COST OF REPAIRS (CONFIRMED)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CENTRE MOULDING	CUT	451.25	451.25
10	REAR BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER LOWER MOULDING	NOT NECESSARY	155.00	-
2	REAR BUMPER BRACKET RH/LH @\$55.80	NOT NECESSARY	111.60	-
	LESS 20% DISCOUNT		-280.15	-90.25
			1,120.60	361.00
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
			230.00	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		480.00	320.00
	SPRAY PAINTING CHARGE.		400.00	200.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	60.00	-
			1,000.00	520.00
	GRAND TOTAL		2,350.60	881.00

Report Ref No. NS/INC20011607/Etd3e2

**CHEN TSUE YEE** 

**Automotive Assessor** 

7

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser