

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20011610/APS3Q2**Date:** 03/12/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	SJQ1050R	Insured Vehicle No :	SHD2252K
Date of Loss:	23/10/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002201

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ1050R	Engine No:	L15A5203269
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Chassis No:	GJ11302813
Reg. Date:	24/04/2009 (Man. Year: 2008)	Odometer:	205238 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,520.88	2,508.08	3,012.80	54.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,290.00	1,310.00	50.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,120.88	3,798.08	4,322.80	53.23
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	8,120.88	3,000.00	5,120.88	63.06
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,407.45		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment: 26/10/2020

Date Inspected: 26/10/2020 Inspected At:

Polymath Garage Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6, #02-02
AUTOBAY
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2020)
Parts: M1-MPV	HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ1050R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	981.50 FL	*- FL
2	1		*FRONT BUMPER SIDE HOLDER LH	Not Necessary	38.50 FL	*- FL
3	1		*HEADLAMP LH	Not Necessary	868.50 FL	*- FL
4	1		*FRONT LH FENDER	Not Necessary	661.20 FL	*- FL
5	1		*FRONT LH FENDER GLASS C/W MOULDING	Cut	325.00 FL	*325.00 FL
6	1		*FRONT LH DOOR	Dented	1,045.60 FL	*1,045.60 FL
7	1		*FRONT LH DOOR LOCK	Not Necessary	314.60 FL	*- FL
8	1		*FRONT LH DOOR WEATHERSTRIPE	Not Necessary	156.70 FL	*- FL
9	1		*FRONT LH DOOR WING MIRROR	Damaged	589.60 FL	*589.60 FL
10	1		*FRONT LH DOOR OUTER HANDLE	Repair	109.50 FL	*- FL
11	1		*REAR LH DOOR	Dented	987.40 FL	*987.40 FL
12	1		*REAR LH DOOR LOCK	Not Necessary	314.60 FL	*- FL
13	1		*REAR LH DOOR WEATHERSTRIPE	Not Necessary	168.20 FL	*- FL
14	1		*REAR LH DOOR OUTER HANDLE	Repair	115.20 FL	*- FL
15	1		*SET FRONT BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
16	1		*FRONT LH FENDER GLASS SEALANT	Necessary	30.00 FS	*30.00 FS
17	1		*FRONT LH DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS
18	1		*REAR LH DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,856.10	3,097.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,335.22	589.52
Total Parts (\$)	5,520.88	2,508.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,000.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	500.00
3	WIRING CHECK	New	50.00	30.00
4	TUFF COAT	New	150.00	50.00
5	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	80.00
6	TO TRANSFER REAR DOOR FITTINGS	New	150.00	80.00
7	TO REMOVE FENDER GLASS	New	100.00	50.00
			Gross Labour Cost (\$\$)	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >