

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011611/R1TF3E2

Date: 16/11/2020

REFERENCE

Insured/Claimant:	ONG CHEW YEN	Policy No:	1900110457	
Date of Loss:	25/10/2020	Nature of Claim:	OD	Claim No: 0448129498SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDZ50X		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGKH740841
Reg. Date:	27/06/2019 (Man. Year: 2018)	Chassis No:	KNAF3416MK5046330
Colour:	White	Odometer:	13623 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,884.42	5,158.80	1,725.62	25.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,090.00	3,010.00	2,080.00	40.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,974.42	8,168.80	3,805.62	31.78
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	11,674.42	7,868.80	3,805.62	32.60
+ GST 7.00/7.00% (\$\$)	817.21	550.82	266.39	32.60
Nett Amount (\$\$)	12,491.63	8,419.62	4,072.01	32.60

INSPECTION

Date of Assignment: 26/10/2020
Date Inspected: 27/10/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY - HOOD	Bent	1,502.00 FL	*1,502.00 FL
2	1		*HINGE ASSY - HOOD, LH	Bent	43.00 FL	*43.00 FL
3	1		*HINGE ASSY - HOOD, RH	Bent	43.00 FL	*43.00 FL
4	1		*PAD - HOOD INSULATING	Serviceable	156.00 FL	*- FL
5	13		*CLIP - HOOD INSULATING PAD MTG	Necessary	13.00 FL	*13.00 FL
6	1		*LATCH ASSY - HOOD	Serviceable	103.00 FL	*- FL
7	1		*LAMP ASSY - HEAD, LH	Broken	2,210.00 FL	*2,210.00 FL
8	1		*ORNAMENT - KIA NO.115	Necessary	32.00 FL	*32.00 FL
9	1		*COVER - FR BUMPER	Deformed	633.00 FL	*633.00 FL
10	1		*GRILLE - FRONT BUMPER	Cracked	485.00 FL	*485.00 FL
11	1		*GRILLE ASSY - RADIATOR	Cracked	328.00 FL	*328.00 FL
12	1		*GARNISH - RADIATOR GRILLE	Cracked	38.00 FL	*38.00 FL
13	1		*MOULDING - FRONT BUMPER, LH	Serviceable	216.00 FL	*- FL
14	1		*ABSORBER - FRONT BUMPER ENERGY	Cracked	84.00 FL	*84.00 FL
15	1		*STIFFENER - FR BPR LWR	Serviceable	114.00 FL	*- FL
16	1		*BRACKET - FR BUMPER UPR SIDE MTG	Serviceable	22.00 FL	*- FL
17	1		*BRACKET - FR BUMPER UPR SIDE MTG	Serviceable	22.00 FL	*- FL
18	1		*WIRING ASSY - BUMPER EXTENSION	Serviceable	207.00 FL	*- FL
19	4		*ULTRASONIC SENSOR ASSY - P.A.S	Serviceable	652.00 FL	*- FL
20	1		*BEAM COMPLETE - FR BUMPER	Serviceable	497.00 FL	*- FL
21	1		*CARRIER ASSY - FRONT END MODULE	Cracked	675.00 FL	*675.00 FL
22	1		*COOLANT (4L)	Not Necessary	26.00 FN	*- FN
23	1		*FRT NUMBER PLATE WITH CASING	Scratched	50.00 FS	*50.00 FS
24	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
25	1		*COVER ASSY-COWL TOP	Deformed	247.00 FL	*247.00 FL
26	1		*GUARD-AIR, LH	Cracked	28.00 FL	*28.00 FL
27	1		*LAMP ASSY-SIDE REPEATER , LH	Serviceable	143.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	8,589.00	6,431.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,698.60	1,272.20
- Nett Item Discount on N Items 23.00/23.00% (\$)	5.98	0.00
Total Parts (\$)	6,884.42	5,158.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER, BONNET & FRT SUPPORT PNL REPAIR LHF FENDER & RHF FENDER.	New	2,000.00	800.00
2	RESPRAY FRT BUMPER, BONNET, LHF FENDER & RHF FENDER.	New	1,400.00	700.00
3	REMOVE & REFIT AC COND & RADIATOR.	New	100.00	0.00
4	TOP UP AIRCON GAS.	New	80.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM.	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
7	REMOVE, REFIT FRT ASSIST PARKING SENSOR.	New	60.00	60.00
8	REPLACE SUPPORT PANEL	New	400.00	400.00
9	REPAIR LH FRONT FENDER	New	200.00	200.00
10	SPRAY PAINT RH FRONT FENDER & LH FRONT FENDER	New	700.00	700.00
Gross Labour Cost (S\$)			5,090.00	3,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >