3/29/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20011612/ERA3Q2

Date:

29/03/2021

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100486884

Claimant Vehicle

SHC595P

Insured Vehicle No:

S1528CD

No: Date of Loss:

23/10/2020

Nature of Claim:

TP

Claim No: 3986397941SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC595P

Make & Model:

TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No:

2ZR2C06397

Reg. Date:

01/04/2019 (Man. Year: 2018)

Chassis No: Odometer:

JTDKB3FU903079813 229772 km

Yes

Colour:

Yellow

Engine Capacity: Market Value/New Car Price:

1798 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Engine Modification: Yes

No

Pre-accident Condition:

CONDITION OF TYRES

Handbrake (Serviceable):

Front Tyre Size: Front Left Side:

195/65 R15 Firestone 4 mm Rear Tyre Size: Rear Left Side:

195/65 R15 Firestone 4 mm

Front Right Side:

Firestone 4 mm

Rear Right Side:

Firestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,539.56	4,656.85	1,882.71	28.79
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,430.00	1,160.00	270.00	18.88
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	7,969.56	5,816.85	2,152.71	27.01
	+ GST 7.00/7.00% (S\$)	557.87	407.18	150.69	27.01
	Nett Amount (S\$)	8,527.43	6,224.03	2,303.40	27.01
	+ Loss of Use (3.5 x S\$50.00/day) (S\$)		175.00		
	+ Car Rental (3.5 x S	S\$126.47/day) (S\$)	442.65		
		(S\$)	6,841.68		
	Liable Amount (50.00%) (S\$)		3,420.84		
	+ Do	c/Search Fee (S\$)	7.49		
		Nett Liability (S\$)	3,428.33		

INSPECTION

Date Inspected:

Date of Assignment:

23/10/2020

23/10/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Lovang Drive Singapore 508969

Estimated Period of Repair:

3.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printrpt&caseid=966073&extid=347437&CFID=83167973&C... 1/4

CHEN TSUE YEE Adjuster: Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

Q1	y Part No.	Particulars	Condition	Repairer's	Amount
1		*COVER FRONT BUMPER	Broken	499.90 FL	*499.90 FL
1		*SUPPORT FRONT BUMPE	Broken	82.30 FL	*82.30 FL
10		*BUMPER PIECE	Necessary	22.00 FL	*22.00 FL
1		*ABSORBER FRONT BUMP	Not Necessary	78.80 FL	*- FL
1		*BRACKET FRT BUMPER	Broken	99.00 FL	*99.00 FL
1		*GRILLE SUB-ASSY RAD	Not Necessary	301.90 FL	*- FL
1		*GRILLE RADIATOR LOW	Not Necessary	166.90 FL	*- FL
1		*COVER FRONT BUMPER	Not Necessary	28.38 FL	*- FL
1		*UNIT ASSY HEADLAMP	Broken	3,455.00 FL	*3,455.00 FL
1		*LAMP ASSY FOG RH	Broken	920.00 FL	*920.00 FL
1		*COVER SUB-ASSY ENGI	Not Necessary	180.80 FL	*- FL
1		*FENDER SUB-ASSY FRO	Dented	945.30 FL	*945.30 FL
1		*EMBLEM SIDE PANEL	Necessary	52.30 FL	*52.30 FL
1		*LINER FRONT FENDER	Not Necessary	198.40 FL	*- FL
1		*WHEEL DISC	Not Necessary	1,555.10 FL	*- FL
1		*FRT FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS
nch	se part. S=SpcN	lett. L=ListItemDisc.			
			Sub Total (S\$)	8,686.08	6,175.80
- List Item Discount on L Items 25.00/25.00% (S\$)			2,146.52	1,518.95	
			Total Parts (S\$)	6,539.56	4,656.85
				Total Parts (S\$) ed during this print-out.	· /

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	our Items						
1	PANEL BEATING	New	800.00	640.00			
2	SPRAYPAINT ON AFFECTED AREA	New	450.00	400.00			
3	CHECK ALL LIGHTING	New	50.00	30.00			
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00			
5	ADJUST FRONT WHEEL ALIGNMENT	New	80.00	60.00			
		Gross Labour Cost (S\$)	1,430.00	1,160.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >