

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7327L**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	IONIQV1 MIRROR ASSY-OUTSI	NOT NECESSARY	1,054.60	-
1	IONIQVC PANEL ASSY-FRONT	DENTED	1,797.20	1,797.20
1	IONIQVC MOULDING ASSY-W/L	CUT	116.20	116.20
1	IONIQVC MOULDING ASSY-W/L	CUT	116.20	116.20
1	IONIQVC MOULDING ASSY-SID	TO REPAIR SEE LABOUR	290.00	-
1	FRT DOOR OUTER MOULDING RH	DENTED	110.10	110.10
	LESS 20% DISCOUNT		-696.86	-427.94
			2,787.44	1,711.76
<b><u>NETT ITEMS</u></b>				
1	(I40) FRT DOOR LOGO CTPL (N)	NECESSARY	75.00	75.00
1	APP LOGO REAR DOOR L/R CT (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
<b><u>LABOUR</u></b>				
	PANEL BEATING (FRT WS PILLAR RH). INCLUSIVE OF THE REPAIR OF IONIQVC MOULDING ASSY-SID.		700.00	480.00
	SPRAYPAINT ON AFFECTED AREA.		850.00	800.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	TRANSFER OF DOOR.		120.00	50.00
			1,770.00	1,390.00
<b>GRAND TOTAL</b>			<b>4,696.94</b>	<b>3,241.26</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>3,241.26</b>

Report Ref No. NS/INC20011617/Eyd3e2


**CHEN TSUE YEE**

Automotive Assessor


**K.K.LAU CPT(RET)**

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.