

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III20011623/GBA3Q2

Date:

10/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: D19MFL0005549_01

Claimant Vehicle No : SGM2931Z**Insured Vehicle No :** YP445U

Date of Loss: 23/10/2020

Nature of Claim:

TP

Claim No: MFL2020D0002190

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGM2931Z**

Make & Model: MITSUBISHI ASX, 2.0 (A)

Engine No: 4B11QT3042

Reg. Date: 15/01/2016 (Man. Year: 2015)

Chassis No: JMFXTGA2WFZC08803

Colour: White

Odometer: 143811 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	238/55 R18	Rear Tyre Size:	238/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,816.00	2,188.00	1,628.00	42.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,520.00	2,310.00	60.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,646.00	3,708.00	3,938.00	51.50
+ GST 7.00/7.00% (S\$)	535.22	259.56	275.66	51.50

Nett Amount (S\$)	8,181.22	3,967.56	4,213.66	51.50
+ Car Rental (3.0 x S\$180.00/day + 7.00% GST) (S\$)		577.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,552.81		

INSPECTION

Date of Assignment: 26/10/2020

Date Inspected: 28/10/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)
 330 Ubi Road 3
 Singapore 408650

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2021)
Parts:	M1-SUV	MITSUBISHI ASX 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM2931Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ,FR BUMPER	Cut	1,036.00 FS	*1,036.00 FS
2	1		*GARNISH ,FR BUMPER CT	Scratched	841.00 FS	*841.00 FS
3	4		*RIVET ,FR BUMPER	Necessary	16.00 FS	*16.00 FS
4	4		*CLIP ,FR BUMPER	Necessary	12.00 FS	*12.00 FS
5	5		*CLIP ,FR BUMPER	Necessary	20.00 FS	*20.00 FS
6	1		*GRILLE ,RADIATOR	Not Necessary	265.00 FS	*- FS
7	1		*MARK ,THREE-DIA	Not Necessary	69.00 FS	*- FS
8	1		*REINFORCEMENT ,FR BUM	Not Necessary	53.00 FS	*- FS
9	1		*REINFORCEMENT ,FR BUM	Not Necessary	415.00 FS	*- FS
10	1		*CORE, FR BUMPER	Not Necessary	10.00 FS	*- FS
11	1		*LH MOULDING ,FR WHEEL	Necessary	132.00 FS	*132.00 FS
12	1		*RH MOULDING ,FR WHEEL	Necessary	131.00 FS	*131.00 FS
13	1		*RH HEADLAMP ASSY	Not Necessary	816.00 FS	*- FS
					Total Parts (S\$)	3,816.00
						2,188.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC /SCANNING	New	250.00	0.00
2	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REPLACE FRONT BUMPER ,REINFORCEMENT ,ETC TO REPAIR HOOD STRAIGHTEN ,REFORM ,ALIGN ON FRONT ACCIDENT AFFECTED AREAS	New	1,800.00	600.00
4	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	New	1,680.00	840.00
Gross Labour Cost (S\$)			3,830.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >