



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2100847

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 08/02/2021
Reference CC6/FCI20011624/Aes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJK 6574U
Insured Veh. SHC 427S
Claim No. D20004349MFSH
Policy No. D-18088937MFSH
Accident Date 24/10/2020
Inspection Date 27/10/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI20011624/Aes3q2	
			Date: 08/02/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 427S	Veh. Inspected	SJK 6574U	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D20004349MFSH	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	26/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053ZEE106120696	Colour	SILVER	
Odometer	188100 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	ALTIMEX	6 mm	
L/H Front Tyre	215/45 R17	ALTIMEX	6 mm	
R/H Rear Tyre	215/45 R17	ALTIMEX	6 mm	
L/H Rear Tyre	215/45 R17	ALTIMEX	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/10/2020	Inspection Date	27/10/2020	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 6574U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BUCKLED	1,217.45	780.00
2	FRONT BONNET HINGE @\$121.35	NOT NECESSARY	242.70	-
1	FRONT BONNET LOCK	NOT NECESSARY	182.10	-
1	FRONT BONNET INNER RUBBER	NOT NECESSARY	174.70	-
1	FRONT BONNET INSULATOR	NOT NECESSARY	374.50	-
2	FRONT HEAD LAMP @\$445.10	CRACKED	890.20	890.20
2	FRONT HEAD LAMP LOWER BRACKET @\$174.80	NOT NECESSARY	349.60	-
1	FRONT BUMPER	DEFORMED	371.45	371.45
16	FRONT BUMPER CLIP @\$6.50	NECESSARY	104.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$122.10	NECESSARY	244.20	110.00
2	FRONT BUMPER FOG LAMP @\$374.10	NOT NECESSARY	748.20	-
2	FRONT BUMPER FOG LAMP COVER @\$174.40	NOT NECESSARY	348.80	-
1	FRONT BUMPER EMBLEM LOGO	NECESSARY	121.10	61.00
1	FRONT BUMPER NUMBER PLATE	CRACKED	50.00	50.00
1	FRONT BUMPER TOP RUBBER	NOT NECESSARY	134.45	-
1	FRONT BUMPER CENTRE LOWER GARNISH	CRACKED	182.20	182.20
1	FRONT BUMPER REINFORCEMENT	BENT	374.40	374.40
2	FRONT FENDER @\$394.50	TO REPAIR SEE LABOUR	789.00	-
1	FRONT GRILLE	CUT	381.45	381.45
1	FRONT GRILLE INNER	NOT NECESSARY	281.75	-
1	FRONT SUPPORT PANEL	BUCKLED	972.40	699.00
1	FRONT AIR-CON CONDENSER	BENT	1,217.85	1,217.85
1	FRONT AIR-CON FAN MOTOR ASSY	NOT NECESSARY	371.10	-
1	FRONT RADIATOR	BENT	974.45	974.45
1	FRONT RADIATOR FAN MOTOR ASSY	CRACKED	378.85	378.85
1	REAR BOOT LID	DENTED	781.45	695.00
2	REAR BOOT LID HINGE @\$182.25	NOT NECESSARY	364.50	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	30.75	30.75
1	REAR BOOT LID ALTIS LOGO	NECESSARY	31.20	31.20
1	REAR BOOT LID 1.6 LOGO	NECESSARY	28.85	28.85

Report Ref No. CC6/FCI20011624/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT LID CENTRE CHROME MOULDING	NOT NECESSARY	374.10	-
2	REAR BOOT LID SIDE REFLECTOR @\$274.10	NOT NECESSARY	548.20	-
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$83.10	NOT NECESSARY	166.20	-
1	REAR BOOT LID INNER LOCK	DAMAGED	136.60	136.60
1	REAR BOOT LID INNER RUBBER	CUT	231.35	231.35
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	371.25	-
8	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	52.00	-
2	REAR TAIL LAMP @\$371.85	CUT	743.70	743.70
2	REAR TAIL LAMP PANEL @\$271.85	TO REPAIR SEE LABOUR	543.70	-
1	REAR BUMPER	DEFORMED	561.60	561.60
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER OUTER @\$107.00	NOT NECESSARY	214.00	-
2	REAR BUMPER SIDE RETAINER INNER @\$92.90	NECESSARY	185.80	185.80
2	REAR BUMPER SIDE REFLECTOR @\$171.45	CRACKED	342.90	145.00
1	REAR BUMPER INNER FOAM	CRACKED	180.90	180.90
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	295.90	-
2	REAR BUMPER REINFORCEMENT BRACKET @\$61.80	DENTED	123.60	123.60
2	REAR BUMPER MUD SHIELD @\$81.10	NOT NECESSARY	162.20	-
12	REAR BUMPER MUD SHIELD CLIP @\$6.50	NOT NECESSARY	78.00	-
2	REAR FENDER @\$971.45	NOT NECESSARY	1,942.90	-
2	REAR FENDER INNER TRIM BOARD @\$381.90	NOT NECESSARY	763.80	-
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	104.00	-
2	REAR FENDER AIR DUCR COVER @\$95.40	NOT NECESSARY	190.80	-
1	REAR END PANEL	DENTED	731.45	580.00
1	REAR END PANEL TOP GARNISH	DEFORMED	371.45	189.00
1	REAR EXHAUST	BENT	792.90	792.90
2	REAR EXHAUST MOUNTING @\$61.10	NOT NECESSARY	122.20	-
1	REAR EXHAUST ALUMINIUM COVER	NOT NECESSARY	182.10	-
1	REAR CENTRE EXHAUST	NOT NECESSARY	972.50	-
1	SPARE TYRE PANEL TOP BOARD	DEFORMED	329.10	329.10
	LESS 25% DISCOUNT		-	-2,879.05

Report Ref No. CC6/FCI20011624/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			24,630.85	8,637.15
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	SPARE TYRE PANEL INSULATION PAD (SN)	NECESSARY	350.00	200.00
			700.00	400.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION & TRIM BOARD .		280.00	60.00
	TO REMOVE & REFIT REVERSE SENSOR .		120.00	50.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST .		380.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN .	NOT NECESSARY	120.00	-
	GUM .	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS.		380.00	120.00
	TO CHECK WIRING .		100.00	60.00
	TUFF KOTE.		150.00	120.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER AND REAR TAIL LAMP PANEL.		3,000.00	1,800.00
	SPRAY PAINTING .		2,800.00	1,800.00
			7,380.00	4,090.00
GRAND TOTAL			32,710.85	13,127.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,500.00

Report Ref No. CC6/FCI20011624/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJK 6574U

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJK 6574U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

