

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20011626/R1BA3Q2

Date: 04/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800033721

Claimant
Vehicle No : SFS7688Z **Insured Vehicle No :** SLX7185K

Date of Loss: 10/10/2020 Nature of Claim: TP Claim No: 7184774495SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFS7688Z	Engine No:	CZD138272
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)	Chassis No:	WVGZZZ1TZJW108288
Reg. Date:	30/07/2018 (Man. Year: 2018)	Odometer:	41977 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,262.15	1,550.12	712.03	31.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,120.00	3,560.00	62.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,942.15	3,670.12	4,272.03	53.79
+ GST 7.00/7.00% (S\$)	555.95	256.91	299.04	53.79
Nett Amount (S\$)	8,498.10	3,927.03	4,571.07	53.79
+ Car Rental (3.0 x S\$80.00/day + 7.00% GST) (S\$)		256.80		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		430.00		
Nett Liability (S\$)		4,615.83		

INSPECTION

Date of Assignment: 28/10/2020

Date Inspected: 28/10/2020 Inspected At: Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,231.02 FS	*1,231.02 FS
2	1		*SPOILER SATIN BLACK	Deformed	319.10 FS	*319.10 FS
3	1		*BUMPER (BUMPER REINFORCEMENT)	Serviceable	508.63 FS	* - FS
4	1		*ATTACHMENT STRIP	Serviceable	60.62 FS	* - FS
5	1		*GUIDE PIECE (BUMPER GUIDE LH)	Serviceable	39.36 FS	* - FS
6	1		*GUIDE PIECE (BUMPER GUIDE RH)	Serviceable	39.36 FS	* - FS
7	1		*GUIDE PIECE (BUMPER BRACKET LH)	Serviceable	32.03 FS	* - FS
8	1		*GUIDE PIECE (BUMPER BRACKET RH)	Serviceable	32.03 FS	* - FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **2,262.15** **1,550.12**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	2,520.00	840.00
2	SPRAY PAINTING	New	2,400.00	800.00
3	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
4	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
Gross Labour Cost (\$\$)			5,680.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >