

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20011651/EQF3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SJW6302A **Insured Vehicle No :** SKA2020T

Date of Loss: 25/10/2020 **Nature of Claim:** TP **Claim No:** CDMPG20001538

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW6302A		
Make & Model:	MERCEDES-BENZ C180, 1.8 CGI (A)	Engine No:	27182030026651
Reg. Date:	06/04/2010 (Man. Year: 2009)	Chassis No:	WDD2040492A360192
Colour:	White	Odometer:	131885 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,535.90	6,494.40	9,041.50	58.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,270.00	2,200.00	63.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,005.90	7,764.40	11,241.50	59.15
Approved Total (Overridden) (\$\$)		6,200.00		
Nett Amount (\$\$)	19,005.90	6,200.00	12,805.90	67.38

INSPECTION

Date of Assignment: 27/10/2020

Date Inspected: 27/10/2020 **Inspected At:**

Asia Motorsports-kaki Bukit (HQ)
15 KAKI BUKIT ROAD 4 #01-05/53
BARTLEY BIZ CENTRE
Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2020)
Parts:	143	MERCEDES-BENZ C180 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW6302A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,480.00 FL	*1,350.00 FL
2	1		*FRONT BUMPER LED DAYLIGHT W/CHROME LHS	Broken	328.00 FL	*142.00 FL
3	1		*FRONT BUMPER LED DAYLIGHT GRILLE COVER	Broken	172.00 FL	*103.00 FL
4	1		*FRONT BUMPER LOWER CHROME MOULDING RH & LH	N/S Cut	204.00 FL	*102.00 FL
5	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	342.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT FRAME	Bent	782.00 FL	*678.00 FL
7	1		*FRONT BUMPER REINFORCEMENT FOAM COVER	Broken	112.00 FL	*112.00 FL
8	1		*FRONT BUMPER SIDE HOLDER RH & LH	N/S Broken	248.00 FL	*124.00 FL
9	1		*FRONT BUMPER UNDER COVER	Not Necessary	375.00 FL	*- FL
10	1		*BONNET	Repair	2,250.00 FL	*- FL
11	2		*BONNET SPRING STOPPER	Not Necessary	248.00 FL	*- FL
12	2		*BONNET INNER LOCK LOWER	Not Necessary	597.00 FL	*- FL
13	2		*BONNET INNER LOCK CATCH	Not Necessary	197.00 FL	*- FL
14	1		*BONNET INSULATOR	Not Necessary	378.00 FL	*- FL
15	1		*BONNET MERC BADGE	Necessary	72.00 FL	*72.00 FL
16	2		*BONNET DAMPERS	Not Necessary	549.00 FL	*- FL
17	1		*FRONT CENTRE RADIATOR CHROME GRILLE	Broken	672.00 FL	*672.00 FL
18	1		*FRONT CENTRE RADIATOR CHROME GRILLE BADGE	Not Necessary	98.00 FL	*- FL
19	1		*LHS FRONT FENDER	Bent	985.00 FL	*897.00 FL
20	1		*LHS FRONT FENDER INNER SPLASH SHIELD	Torn	260.00 FL	*260.00 FL
21	1		*WIPER WASHER TANK	Not Necessary	372.00 FL	*- FL
22	1		*LHS HEADLAMP	Broken	1,980.00 FL	*1,610.00 FL
23	1		*LHS HEADLAMP TOP PANEL	Not Necessary	324.00 FL	*- FL
24	1		*LHS FRONT SHOCK ABSORBER	Not Necessary	592.00 FL	*- FL
25	1		*LHS FRONT TIE ROD	Not Necessary	198.00 FL	*- FL
26	1		*LHS FRONT LOWER CONTROL ARM	Not Necessary	375.00 FL	*- FL
27	1		*LHS FRONT UPPER CONTROL ARM	Not Necessary	375.00 FL	*- FL
28	1		*LHS FRONT WHEEL BEARING	Jammed	294.00 FL	*294.00 FL
29	1		*LHS FRONT KNUCKLE ARM	Not Necessary	492.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*SET LHS FRONT FENDER INNER SPLASH SHIELD CLIPS	Necessary	80.00 FS	*20.00 FS
31	1		*LHS FRONT SPORTS RIM	Cut	1,280.00 FS	*700.00 FS
32	1		*LHS FRONT TYRE 80%	Not Necessary	280.00 FS	*- FS
33	1		*SET BONNET INSULATOR CLIPS	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,071.00	7,136.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,535.10	641.60
Total Parts (\$\$)					15,535.90	6,494.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,400.00	500.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,000.00	600.00
3	TO REMOVE AND CHECK WIRING OF ALL ELECTRICAL COMPONENTS AND FOCUS HEADLAMP BEAM	New	200.00	30.00
4	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATIONS	New	300.00	0.00
5	TO REMOVE AND REPLACE LHS FRONT UNDERCARRIAGE PARTS (SUSPENSION COMPONENTS)	New	300.00	50.00
6	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST	New	120.00	60.00
7	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (S\$)			3,470.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >