

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20011652/ETF3Q2

Date: 09/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant
Vehicle No : SMP191T

Insured Vehicle No : SHA3642C

Date of Loss: 22/10/2020

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP191T**

Make & Model: HONDA ACCORD, 1.6 (M)

Engine No: 2AR1313615

Reg. Date: 02/11/2015 (Man. Year: 2015)

Chassis No: AGH300026290

Colour: Black

Odometer: 81609 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size:

215/50 R17

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,090.00	4,520.20	6,569.80	59.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	2,550.00	1,060.00	29.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,700.00	7,070.20	7,629.80	51.90
Approved Total (Overridden) (S\$)		5,650.00		
Nett Amount (S\$)	14,700.00	5,650.00	9,050.00	61.56

INSPECTION

Date of Assignment: 27/10/2020

Date Inspected: 28/10/2020 Inspected At:

Car Pro Auto (HQ)

Blk 6 Yew Tee Industrial Estate 399-J,

Woodlands Road

Singapore 678008

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2020)
Parts:	143	HONDA ACCORD 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP191T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR (LH)	Dented	1,650.00 FL	*1,650.00 FL
2	1		*REAR DOOR MOULDING LH	Not Necessary	455.00 FL	*- FL
3	1		*REAR DOOR MOTOR (LH)	Not Necessary	1,550.00 FL	*- FL
4	1		*REAR DOOR HANDLE (LH)	Not Necessary	230.00 FL	*- FL
5	1		*REAR DOOR INNER LOCK LH	Not Necessary	355.00 FL	*- FL
6	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	395.00 FL	*- FL
7	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	298.00 FL	*- FL
8	1		*FLOOR DOOR LH	Dented	1,250.00 FL	*1,250.00 FL
9	1		*FRONT DOOR INNER TRM BOARD LH	Not Necessary	325.00 FL	*- FL
10	1		*FRONT DOOR INNER LOCK LH	Not Necessary	355.00 FL	*- FL
11	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	298.00 FL	*- FL
12	1		*FRONT DOOR MOULDING LH	Not Necessary	400.00 FL	*- FL
13	1		*REAR LH FENDER	Repair	990.00 FL	*- FL
14	1		*REAR LH FENDER INNER SHIELD	Torn	198.00 FL	*198.00 FL
15	1		*REAR LH FENDER INNER SHIELD FASTENERS	Necessary	25.00 FL	*25.00 FL
16	1		*REAR BUMPER	Broken	750.00 FL	*750.00 FL
17	1		*REAR BUMPER LH SIDE RETAINER	Broken	38.00 FL	*38.00 FL
18	1		*REAR BUMPER BRACKET LH	Not Necessary	115.00 FL	*- FL
19	1		*REAR LH ABSORBER	Not Necessary	325.00 FL	*- FL
20	1		*REAR LH WHEEL BEARING	Jammed	698.00 FL	*422.60 FL
21	1		*REAR LH KNUCKLE ARM	Not Necessary	670.00 FL	*- FL
22	1		*REAR LH LOWER ARM	Not Necessary	620.00 FL	*- FL
23	1		*REAR LH WHEEL HUB	Not Necessary	350.00 FL	*- FL
24	1		*WINDOW MOULDING LH	Not Necessary	85.00 FS	*- FS
25	1		*REAR LH RIM	Cut	350.00 FS	*350.00 FS
26	1		*REAR LH TYRE	Not Necessary	280.00 FS	*- FS
27	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
28	1		*FRONT LH DOOR CHROME MOULDING	Cut	200.00 FS	*200.00 FS
29	1		*REAR LH DOOR CHROME MOULDING	Cut	200.00 FS	*200.00 FS
30	1		*FRONT LH DOOR SIDE SKIRT GARNISH	Broken	200.00 FS	*200.00 FS
31	1		*REAR LH DOOR SIDE SKIRT GARNISH	Broken	200.00 FS	*200.00 FS
32	1		*REAR LH DOOR SIDE SKIRT CORNER GARNISH	Broken	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,175.00	5,603.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,085.00	1,083.40
Total Parts (\$\$)	11,090.00	4,520.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPOSITIONING REPLACEMENT PARTS	New	1,200.00	1,100.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	1,000.00	1,000.00
3	TO REMOVE N REPLACE FRONT AND REAR DOOR COMPONENTS	New	250.00	100.00
4	TO CHECK WIRING SYSTEM FOR PROPER FUNCTIONS	New	60.00	30.00
5	TO DISMANTLE & REFIX FRONT AND REAR DOOR WINDOW	New	250.00	100.00
6	TO CARRY OUT ANTI RUST TREATMENT	New	150.00	30.00
7	TO REMOVE AND REINSTALL REAR LH UNDERCARRIAGE ITEM	New	250.00	100.00
8	TO REMOVE AND REFIX REVERSE SENSOR	New	80.00	30.00
9	TO PERFORM 4 WHEEL ALIGNMENT	New	100.00	60.00
10	TO REMOVE AND REINSTALL FUEL COMPONENTS	New	150.00	0.00
11	TO REMOVE AND REINSTALL REAR LH WINDSCREEN	New	120.00	0.00
Gross Labour Cost (\$\$)			3,610.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >