

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748

WORKSHOP ESTIMATE

| | |
|-----------------------------------|-------------|
| Rear bumper | damaged |
| Rear bumper reinforcement | fractured |
| Rear bumper reinforcement bracket | serviceable |
| Sensor | malfunction |
| Labour charges | |
| Spray | |
| Anti rust | |
| replace sensor | |

| Repair Cost Summary | | | |
|--|-----|--|------------|
| Hua Meng Spray Painting Workshop Assessment Excluding GST | | LBS Auto Consultants Pte Ltd Assessment Excluding GST | |
| Labour: | NIL | Labour: | \$700.00 |
| Paint Labour: | NIL | Paint Labour: | \$500.00 |
| Parts: | NIL | Parts: | \$1,000.00 |
| Total: | NIL | Total: | \$2,200.00 |
| Lump Sum Less 20%: | | Lump Sum Less 20%: | |
| The repairs will take 04 working days to complete. | | | |

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748

| Vehicle Survey Report | | | |
|-------------------------|--|---|----------------------------------|
| Insurer: | Direct Asia Insurance (Singapore) Pte. Ltd. | Claim Number: | 96308 |
| Workshop: | Hua Meng Spray Painting Workshop | Claim Type: | PRI |
| Vehicle make & model: | Hyundai Avante | Vehicle number: | SJR7374L Engine Capacity:1591 |
| Registration date: | 13.07.2009 | Vehicle Mileage: | 115730 |
| Chassis No: | KMH DU41BR9U774252 | Engine No: | G4FC9U663367 |
| Economic Repair Limit | Market Value: \$38,000.00 PARF/COE Rebate: \$24,221.00 Repair Limit: \$13,879.00 | Part by Part Repair or Lump Sum Repair: | Part by Part Repair |
| Workshop Estimate Cost: | NIL | Surveyor Estimated Repair Cost: | SGD \$2,200.00 + GST |
| Days to Repair: | 04 days | OD Excess Applicable: | NIL |
| Assessor: | T. Thiyagarajan | Date & Time of Assessment: | 31.01.2020 @ 1650hrs |
| NIMA Protocol: | | 1 st Inspection was done with the dismantling of hidden parts | |
| | | 1 st Inspection was done without the dismantling of hidden parts | |
| | | 2 nd Inspection was done where hidden damaged parts were dismantled in the presence of the Surveyor and not before | |
| | ✓ | 2 nd Inspection was done where hidden damaged parts were dismantled not in the presence of the Surveyor | |

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 02-20001/DY

Billing Name & Address
Goh Kee Hui Daron
Blk 105 Bedok Reservoir Road
#08-398
Singapore 470105

Date 25 Feb 2020

Vehicle No : SJR 7374 L

Model : Hyundai Avante

| Item | Descriptions | Amount S\$ |
|------|---|------------------|
| 1 | Date of inspection : <u>1 Feb 2020</u> A copy of the inspection / survey report Correspondence, postages and etc. | |
| 2 | Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>105</u> copies | |
| 3 | Transportation Charges | |
| 4 | 2nd Inspection & Final Inspection | |
| | Total | <u>\$ 645.00</u> |
| | SDLS : SIX HUNDRED AND FORTY-FIVE ONLY | |

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 02-20001/DY / 2020

Date of Report : 25 Feb 2020

Goh Kee Hui Daron
Blk 105 Bedok Reservoir Road
#08-398
Singapore 470105

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 29 Jan 2020

As per your instruction dated 1 Feb 2020
carried out a physical inspection on the said vehicle
our report and findings as follows:

with regard to the above matter. We have
SJR 7374 L . We enclosed herewith

1. VEHICLE PARTICULARS

Registration No : SJR 7374 L
Model : Hyundai Avante
Year / Capacity : 2009/1591
Chassis No : KMH DU41BR9U774252
Engine No : G4FC9U663367
Mileage : 115730
Colour : Maroon

2. TYRES CONDITION

| | | | <u>Size</u> | <u>Made</u> | <u>Balance</u> | | <u>Rim</u> |
|-------|-----|---|-------------|-------------|----------------|----|------------|
| FRONT | O/S | : | 215/45 R17 | Kumho | 7.00 | mm | Sport |
| REAR | O/S | : | 215/45 R17 | Kumho | 7.00 | mm | Sport |
| FRONT | N/S | : | 215/45 R17 | Kumho | 7.00 | mm | Sport |
| REAR | N/S | : | 215/45 R17 | Kumho | 7.00 | mm | Sport |

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Hua Meng Spray Painting Workshop
No. 1 Kaki Bukit Avenue 6
#01-61/34 AutoBay @ Kaki Bukit
Singapore 417883

5. Estimated normal period of repair : 6 working days to complete.

6. Enclosed number of photograph : 105 copies.

7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SJR 7374 L**
 Report No: **TP/ 02-20001/DY / 2020**

SPARE PARTS

| Qty | Parts Description | Condition | Workshop's Estimation | Our Revised Estimation |
|---------------------------|---------------------------------|-----------|-----------------------|------------------------|
| <u>List Items</u> | | | | |
| 1 | Boot lid | Damage | \$ 886.00 | \$ 886.00 ✓ |
| 2 | Boot lid hinges | Intact | \$ 225.40 | \$ + |
| 2 | Boot lid lamps | Intact | \$ 336.00 | \$ + |
| 2 | Rear taillamps | Damage | \$ 533.00 | \$ 533.00 ✓ |
| 1 | Rear end panel | Damage | \$ 537.90 | \$ 537.90 ✓ |
| 1 | Rear end panel inner garnish | Damage | \$ 69.50 | \$ 69.50 ✓ |
| 1 | Rear bumper | Damage | \$ 442.00 | \$ 442.00 ✓ |
| 1 | Rear bumper reinforcement | Damage | \$ 262.00 | \$ 262.00 ✓ |
| 2 | Rear bumper reinforcement stays | Damage | \$ 134.80 | \$ 134.80 ✓ |
| 1 | Rear spare tyre panel | Repair | \$ 783.00 | \$ |
| | | | <u>\$ 4209.60</u> | <u>\$ 2865.20</u> |
| | Discount | 20.0% | \$ 841.92 | \$ 573.04 |
| | | | <u>\$ 3367.68</u> | <u>\$ 2292.16</u> |
| <u>Special Nett Items</u> | | | | |
| 1 | Rear reverse sensor (1 set) | Damage | \$ 280.00 | \$ 280.00 ✓ 220 |
| | | | <u>\$ 280.00</u> | <u>\$ 280.00</u> |

220

Spare Parts Total \$ 3647.68 \$ 2572.16

Vehicle No: **SJR 7374 L**
Report No: **TP/ 02-20001/DY / 2020**

LABOUR COST

| S/No | Job Descriptions | Workshop's Estimation | Our Revised Estimation |
|--------------|---|-----------------------|------------------------|
| | Spare Parts Total c/f | \$ 3647.68 | \$ 2572.16 |
| 1 | To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts. | \$ 50.00 | \$ 40.00 30 |
| 2 | To remove and refit inner trims, inner garnishes, to facilitate the repairs. | \$ 180.00 | \$ 80.00 ✓ |
| 3 | To remove and refit rear bumper sensor. | \$ 150.00 | \$ 80.00 50 |
| 4 | To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools. | \$ 900.00 | \$ 660.00 ✓ |
| 5 | To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available. | \$ 1050.00 | \$ 880.00 <i>rw</i> |
| 6 | To apply undercoating on the repaired and replaced panels for rust protection. | \$ 150.00 | \$ 90.00 80 |
| | | 1710 | |
| Total | | \$ 6127.68 | \$ 4402.16 |

Recommended PART BY PART Repair Amount of: **\$ 4402.16**

SDLS: FOUR THOUSAND FOUR HUNDRED TWO AND CENTS SIXTEEN ONLY



Qualified Appraiser

total 4222.16
4/5: 3.81c (10%)
05Days