

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CS/ICS20011667/49f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGJ 4732J

at Workshop m/s

NPH

of

Insured:

SKC9731H

Policy No.

Claims No.

DMPC2000180H/02/CT

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

30k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGJ 4732J

Yr Regn:

7.06

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota Corolla Altis c.c. 1598

Colour

Beige

A/C:

Insured / Std / NI / NA

Sp. Reading

129377

T/Radio: Insured / Std / NI / NA

Eng/No:

MR0532EC107123917

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

mm

L/Bal.

6 mm

L/Bal.

mm

D.O.A.

23/10/20

D.O.I.

28/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3.10.20 LTA # 25484 we 31-5-2026
confirmed 4/5 @ 1900 with AM Boi (Red \$1182.01, 38%)

Date/Time, File Pass to?

☐

Preli. Report

1) 02/4/2024

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS. \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

MER-TP

Lump Sum / I.B.F. (\$

1900

TOTAL



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : TP0040/10/20 Date : 26/10/2020

THIRD PARTY CLAIM

M/S : HO SUSIE
BLK 544 PASIR RIS STREET 51
#05-03
SINGAPORE 510544

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SGJ4732J - TOYOTA ALTIS
INSURED : HO SUSIE
DATE OF ACCIDENT : 23/10/2020
POLICY NO :

ENGINE# :
CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$
Replacement of Parts				
1 front door protector <i>scr/nee</i>	10	40.00	40.00	40.00 ✓
2 front door chrome moulding <i>nee</i>	10	25.00	25.00	25.00 ✓
3 rear door protector <i>scr/nee</i>	10	35.00	35.00	35.00 ✓
4 rear door chrome moulding <i>nee</i>	10	23.02	23.02	23.02 ✓
5 rear door RH <i>scr/nee</i>	10	1060.00	1060.00	1,060.00 ✓
6 rear door w/strip rubber <i>17</i>	10	58.00	58.00	58.00 X
7 rear bumper <i>7011</i>	10	395.00	395.00	395.00 ✓
				1,636.02
Less 25%				-409.01
Total Material				\$1,227.01
Labour & Misc				

- 1 Remove & install r/door, r/bumper, knock f/door, r/fender, wheel arch panel and restraighthen body & chassis.
- 2 Spray painting.
- 3 Check wiring system.
- 4 Remove & install rear boot carpet.

400 750.00
800 1,000.00
20 25.00
60 80.00
1,855.00

Total Labour

Nett Total Before Gst

\$1,855.00
\$3,082.01

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illicit modification(s) is allowed
• Supplemental part(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

not Ackd
2/s *\$1900*
4 days
28/10/20
Whebe Office

7-1578.02
252
118357
1280.00
2463.57
1970.4