CO. REG. NO: 199402370D GST NO: M2-0123250-3

### AUTO PTE LTD

# 金興(襲)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21, Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895 Email: service@kkimhin.com.sg

SURER:

Lonpac Insurance Bhd (HQ)

ARTICULARS OF CLAIM	AF	ITS	CU	LARS	OF	CLAIL	W
---------------------	----	-----	----	------	----	-------	---

laim Type:

olicy No:

ehicle Reg. No.: river Age/Info:

Injury Involved?

sured/Claimant:

iver:

OD (OWN DAMAGE)

Z/20/VC06/105804

GBB5815Z 23 / MALE

YES LANDSCAPE ENGINEERING PTE LTD

**DURAIKANNU SELVAM** 

TOYOTA DYNA 150 MANUAL

3SEATER, 3.0 D (M)

SILVER 1KD1926564

0 KM

int Type:

marks:

ake/Model:

gine No:

dometer:

hicle Colour:

tal Loss?

t. Duration of Repair (day) 14 / 2 day,

Ref. No:

Date of Loss:

21/10/2020

Driveable?

Party At Fault:

UNKNOWN

Third Party Involved? YES

Vehicle Reg. Date: 08/07/2009

Chassis No:

JTFAT35Y60K200615

Nos Norhanies Berny After Paint

scription of Accident/Loss

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT.

VEHICLE HAS BEEN TOWED IN TO WORKSHOP. PLS ARRANGE FOR SURVEY.

THANK YOU - SANDRA

sent Location:

18x1 6256 4315

ST OF CLAIMS

ts cellaneous Items our

ntwork Labour

ing

K KIM HIN AUTO PTE LTD (HQ)KK Auto Consultants hence notify the Repairer of the following: · To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis

 No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: Gross Total (S\$)

+ GST 7.00% (S\$)

23,379.25 1,636.55

Nett Amount (S\$)

25,015.80

Amount

0.00

0.00

0.00

18,869.25

4,510.00

claim is handled by: SANDRA KHONG YEE TENG

## IR DETAILS

erence

(Last Synchronised: 27 Oct 2020) t Source:

TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database) arts:

(Price-denominated Standard List) Repairer's Labour: Print Code: (Unsubmitted, no print-code for GBB5815Z)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

	Qty Part No.	Particulars	9/	Disc	%Depr		Amount	
4	1	*FRONT WINDSCREEN GLASS		0.00	0.00	cm	*490.00 F	
2	1	*FRONT WINDSCREEN GLASS RUBBER		0.00	0.00	New	*105.00 F	
3	1	*N/S FRONT DOOR		0.00	0.00	R	*580.00 F	0111
J 4		*N/S FRONT DOOR VERTICAL GARNISH		0.00	0.00	an	*40.00 F	
5	1	*N/S FRONT DOOR OUTER MOULDING		0.00	0.00	Del		
6	1	*N/S FRONT DOOR GLASS	Sharpend	0.00	0.00		*190.00 F	
7	4	*N/S FRONT DOOR GLASS  *N/S FRONT DOOR INNER MOULDING		0.00	0.00	as	*55.00 F	
8	1	*N/S FRONT DOOR GLASS RUN CHANNEL		0.00	0.00	Rel	*95.00 F	
9	1	*N/S FRONT DOOR REGULATOR		0.00	0.00		*120.00 F	
10	1	*N/S FRONT DOOR REGULATOR MOTOR		0.00	0.00		*195.00 F	
11	1	*N/S FRONT DOOR OUTER PULL HANDLE		0.00	0.00		*75.00 F	
12	1	*N/S FRONT DOOR OUTER FOLL HANDLE	Mycm		0.00		*280.00 F	
	-	*N/S FRONT DOOR LOCK	. /000	0.00	0.00	Ja	*175.00 F	_
13		*N/S FRONT DOOR WEATHERSTRIP	Cor	0.00	0.00		*80.00 F	2
14	1	*N/S FRONT DOOR STEP GARNISH	cor	0.00	0.00	In	*110.00 F	
15	1			0.00	0.00	Cu	*45.00 F	
16	1	*N/S FRONT DOOR OUTER SIDE PROTECTOR		0.00	0.00	41	*75.00 F	
17	!	*N/S FRONT DOOR OUTER SPLASH SHIELD		0.00	0.00		*30.00 F	
18	1	*N/S WINGMIRROR STAY CAP COVER - BLACK		0.00	0.00		*460.00 F	
19	1	*B PILLAR OUTER LH	И	0.00	0.00	7	*285.00 F	
20	1	*B PILLAR INNER REINFORCEMENT	^	0.00	0.00	R	*45.00 F	
21	1	*B PILLAR INNER UPPER PLATE		0.00	0.00	By	*250.00 F	
22	1	*A PILLAR OUTER LH	NJ		-	17	*85.00 F	
23	1	*N/S FRONT DOOR FRAME WEATHERSTRIP	""	0.00	0.00	an		
24	1	*N/S HEADLAMP		0.00	0.00	Ry	210.00	
25	1	*CABIN BACK PANEL		0.00	0.00	R	*520.00 F	
26	1	*CABIN BACK PANEL TOP REINFORCEMENT		0.00	0.00		*145.00 F	
27	1	*CABIN INTERIOR REAR VIEW MIRROR		0.00	0.00		*95.00 F	
28	1	*ROOF TOP PANEL	Neform	0.00	0.00		*600.00 F	1
29	1	*ROOF TOP PANEL TRIM LINING		0.00	0.00	0	1,150.00 F	
30	1	*CARGO DECK REAR PARTITION		0.00	0.00		*680.00 F	
31	2	*CARGO DECK REAR PARTITION LOCK LH/RH	B-11017	0.00	0.00		*190.00 F	
32	2	*FRONT LOWER ARM LH/RH			0.00		*440.00 F	
33	2	*FRONT LOWER ARM BALL JOINT LH/RH		0.00	0.00		*190.00 F	-
34	2	*FRONT UPPER ARM LH/RH	M		0.00		*480.00 F	
35	2	*FRONT KNUCKLE ARM LH/RH	By	0.00	0.00		*780.00 F	7
36	2	*FRONT KNUCKLE ARM BEARING LH/RH	M	0.00	0.00		*130.00 F	7
37	2	*FRONT SHOCK ABSORBER LH/RH	Ry	0.00	0.00		*120.00 F	-
38	2	*FRONT STABILIZER BAR BUSH	M	0.00	0.00		*30.00 F	7
39	2	*FRONT STABILIZER BAR LINKAGE LH/RH	1,022,000,000	0.00	0.00		*50.00 F	7
40	2	*ENGINE MOUNTING LH/RH	CM	0.00	0.00		*130.00 F	
41	2	*GEAR BOX MOUNTING	CRA	0.00	0.00		*110.00 F	
42	2	*CABIN FRONT MOUNTING LH/RH	In	0.00	0.00		*370.00 F	
43	2	*CABIN REAR MOUNTING LH/RH	In	0.00	0.00		*490.00 F	*
44	1	*CABIN TILT PULL LEVER	111	0.00	0.00		*290.00 F	1
45	1	*CABIN TILT PULL LOCK	Dil	0.00	0.00		*320.00 F	7
46	1	*CABIN TILT PULL LEVEL LINKAGE	R	0.00	0.00		*235.00 F	X
47	1	*RADIATOR	Pn	0.00	0.00		*580.00 F	2
	1	*RADIATOR FAN BLADE	CRA	0.00	0.00		*90.00 F	2

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

Oty Part No.	Particulars		%Disc	%Depr		,
1 1 2 2 2 1	*RADIATOR FAN CLUTCH *CARGO DECK CANOPY 1500SN *FRONT TYRE LH/RH *FRONT RIM LH/RH *RADIATOR COOLING	100000 (Interes) ? Alt proofs of	A 0 0 0 0 0	0.00	*3,500.00 FS 288SN *360.00 FS	sosn
Franchise part. S=SpcNett.		Sub Total (S\$) + Margin on L,N Items 15.00% (S\$)			16,983.00 1,886.25	
		Total Parts (S\$)			18,869.25	
	Report was u Generated u	nsubmitted during this print-out. sing Merimen e-Claims IEAS				

are no new miscellaneous items selected.

Estimates on	Labour
--------------	--------

Estimates on Labour	Lab.Type	Amount
No Particulars		1800
Abour Items TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO	New	2,200.00
RENEW AFFECTED PARTS	New	80.00
TO REMOVE DOORS FITTINGS	New	100.00 6
TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	100.00
TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS	New	220.00
TO REMOVE FRONT INSTRUMENT PANEL AND REWIRING TO FACILITATE REPAIR WORKS	New	300.00 2
TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS	New	80.00
TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	9001 1,400.00
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	30.00
TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION	140	
Gross Labou	r Cost (S\$)	4,510.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

Report Format: Lump Sum | I.B.I: (S