

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No: 199607198R GST Reg. No. 19-9607198-R | | | | |
|--|---|--|------------------|------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI20011677/Gsf3e2 | | | | | |
| (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 | | | Date: 02-11-2020 | | |
| | | | Code: AGI | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLX 6067A | Veh. Inspected | SMJ 2433P | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | C10007748 | Excess (\$) | 0.00 | |
| | Assign From | IVY RATILLA | Assign Date | 27/10/2020 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | MITSUBISHI LANCER 1.6 | c.c | 1584 | |
| | Engine No. | HIDDEN | Year of Reg. | 2006 | |
| | Chassis No. | JMYSTCS3A6U009300 | Colour | BLACK | |
| | Odometer | 228676 | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 195/60 R15 | GOODYEAR | 6 mm | |
| | L/H Front Tyre | 195/60 R15 | GOODYEAR | 6 mm | |
| | R/H Rear Tyre | 195/60 R15 | GOODYEAR | 6 mm | |
| | L/H Rear Tyre | 195/60 R15 | GOODYEAR | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 26/10/2020 | Inspection Date | 28/10/2020 | |
| | Survey held at | BIFROST AUTO PTE LTD | | | |
| | | 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875 | | | |
| 5a. | _ | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | | | | | |

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: