

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20011689/UPA3Q2

Date: 05/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBH4809S **Insured Vehicle No :** SML7552K

Date of Loss: 14/10/2020 **Nature of Claim:** TP **Claim No:** 4645403727SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4809S		
Make & Model:	NISSAN NV350, 2.5 (A)	Engine No:	YD25423802A
Reg. Date:	18/06/2018 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0008790
Colour:	Silver	Odometer:	79146 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,302.70	1,174.32	2,128.38	64.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	840.00	740.00	46.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,882.70	2,014.32	2,868.38	58.75
Approved Total (Overridden) (\$\$)		1,600.00		
Nett Amount (\$\$)	4,882.70	1,600.00	3,282.70	67.23
+ Car Rental (4.0 x S\$130.00/day) (\$\$)		520.00		
Nett Liability (\$\$)		2,120.00		
Global Sum Settlement (\$\$)		2,000.00		

INSPECTION

Date of Assignment: 09/11/2020

Date Inspected: 09/11/2020 Inspected At:

Leang Automotive (HQ)
BLK 1 KAKI BUKIT AVE 6 #02-12
AUTOBAY@ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	571.90 F	*571.90 FL
2	1		*FRONT BUMPER SIDE RETAINER N/S	Cracked	181.00 F	*181.00 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
4	1		*FRONT BUMPER FOG LAMP N/S	Cracked	120.60 F	*120.60 FL
5	1		*FRONT BUMPER BEAM	Not Necessary	705.00 F	*- FL
6	1		*HEADLAMP N/S	Scratched	401.30 F	*401.30 FL
7	1		*FRONT DOOR N/S	Repair	1,071.90 F	*- FL
8	1		*FRONT DOOR STEP GARNISH N/S	Repair	221.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,302.70	1,304.80
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	130.48
Total Parts (\$)	3,302.70	1,174.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO TRANSFER FRT DOOR MECHANISM	New	80.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	300.00
5	TO PUTTY & SPRAY PAINTING & ROC STICKER	New	800.00	520.00
Gross Labour Cost (\$\$)			1,580.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >