

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20011693/UGS3Q2

Date: 08/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070119070

Claimant
Vehicle No : FBM3523X **Insured Vehicle No :** EK448A

Date of Loss: 25/10/2020 Nature of Claim: TP Claim No: 7198580841SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM3523X		
Make & Model:	SUZUKI UH200A, 200cc	Engine No:	H405403951
Reg. Date:	03/10/2017 (Man. Year: 2017)	Chassis No:	MLCC91327H0403951
Colour:	Grey	Odometer:	0 km
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/90-13	Rear Tyre Size:	130/70-12
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,603.00	8,452.60	6,150.40	42.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	880.00	700.00	44.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,183.00	9,332.60	6,850.40	42.33
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	16,183.00	7,100.00	9,083.00	56.13
+ GST 7.00/7.00% (S\$)	1,132.81	497.00	635.81	56.13
Nett Amount (S\$)	17,315.81	7,597.00	9,718.81	56.13
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		7,779.00		

INSPECTION

Date of Assignment: 27/10/2020

Date Inspected: 27/10/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FORK ASSY	Bent/Twisted	1,150.00 F	*680.00 FL
2	1	*WINDSHIELD	Cracked	968.00 F	*750.00 FL
3	1	*HEADLAMP	Cracked	655.00 F	*520.00 FL
4	1	*LAMP STAY	Serviceable	225.00 F	*- FL
5	1	*FRONT FENDER	Cracked	165.00 F	*145.00 FL
6	1	*SET FRONT FAIRING COVER	Broken	1,500.00 F	*1,250.00 FL
7	1	*SIDE MIRRORS	N/s Scratched	310.00 F	*155.00 FL
8	1	*HANDLE BAR	Serviceable	135.00 F	*- FL
9	2	*HANDLE BAR BALANCERS	Not Necessary	100.00 F	*- FL
10	1	*HANDLE BAR GRIP	Not Necessary	55.00 F	*- FL
11	1	*BRAKE LEVER LH	Serviceable	150.00 F	*- FL
12	1	*BRAKE LEVER RH	Scratched	150.00 F	*115.00 FL
13	1	*FRONT SIGNAL LAMPS	O/s Cracked	330.00 F	*105.00 FL
14	2	*LOWER BELLY PANELS	Distorted	900.00 F	*700.00 FL
15	2	*LOWER COWLING CENTRE GRILLES	Distorted	360.00 F	*360.00 FL
16	2	*FOOT STEP GARNISHS	Distorted	370.00 F	*370.00 FL
17	2	*FOOT STEPS	Distorted	170.00 F	*170.00 FL
18	1	*REAR EXHAUST	Dented/Bent	1,650.00 F	*1,450.00 FL
19	1	*REAR EXHAUST FRONT COVER	Distorted	65.00 F	*65.00 FL
20	1	*REAR EXHAUST CENTRE COVER	Cut	99.00 F	*99.00 FL
21	1	*REAR EXHAUST REAR COVER	Cut	60.00 F	*60.00 FL
22	1	*TAILLAMP	Not Necessary	355.00 F	*- FL
23	1	*METER	Not Necessary	850.00 F	*- FL
24	1	*METER COVER	Cracked	388.00 F	*300.00 FL
25	1	*FRONT INNER CENTRE COVER	Cracked	620.00 F	*485.00 FL
26	1	*FRONT INNER CENTRE COVER COVER	Cracked	350.00 F	*290.00 FL
27	1	*MAIN STAND	Repair	158.00 F	*- FL
28	1	*SIDE STAND	Repair	125.00 F	*- FL
29	1	*ENGINE COVER	Scratched	350.00 F	*245.00 FL
30	1	*FRONT WINDSHIELD FRT LICENCE PLATE STICKER	Necessary	20.00 FS	*10.00 FS
31	1	*SET FRONT WINDSHIELD STICKER	Not Necessary	100.00 FS	*- FS
32	1	*SET FRONT FENDER ABS STICKER	Necessary	60.00 FS	*30.00 FS
33	1	*SET FRONT LED LAMP	Damaged	500.00 FS	*250.00 FS
34	1	*REAR BOX	Dented/Bent	980.00 FS	*680.00 FS
35	1	*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,603.00 9,284.00
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 831.40

Total Parts (\$\$) 14,603.00 8,452.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	30.00	0.00
2	TO STRAIGHTEN FRONT BODY ALIGNMENT	New	450.00	300.00
3	TO SPRAY PAINTING	New	600.00	280.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	500.00	300.00
Gross Labour Cost (\$\$)			1,580.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >