



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 2938U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SIDE STAND	BROKEN	250.00	185.00
1	MAIN STAND	TO REPAIR SEE LABOUR	150.00	-
1	SWING ARM	BENT / TWISTED	700.00	350.00
1	GEAR CHAIN REAR	NOT NECESSARY	300.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	350.00	-
1	REAR SHOCK ABSORBER SPRING	NOT NECESSARY	300.00	-
1	SIDE BRACKET LEFT RIDER BRACKET	FRT BENT	180.00	180.00
1	N/S FOOT REST	BROKEN	200.00	68.00
1	REAR EXHAUST BRACKET	CUT	35.00	35.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	785.00	-
1	REAR EXHAUST HEAT SHIELD	SCRATCHED	75.00	75.00
1	FOOT BRAKE PEDAL	CUT	65.00	65.00
2	FRONT FOOT RESTS @\$68.00	O/S CUT / N/S REPEATED	136.00	68.00
1	HANDLE BAR	BENT	165.00	165.00
1	O/S FRONT BALANCER	SCRATCHED	30.00	30.00
1	O/S FRONT BRAKE LEVER	SCRATCHED	105.00	105.00
1	O/S FRONT MIRROR	CUT	112.00	112.00
1	O/S FRONT SIGNAL LAMP	CUT	75.00	75.00
2	REAR FOOT RESTS @\$85.00	N/S TWISTED / O/S CUT	170.00	170.00
1	O/S FRONT HANDLE GRIP	TORN	62.00	62.00
	LESS 10% DISCOUNT		-424.50	-174.50
			3,820.50	1,570.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR WHEEL RIM (SN)	NOT NECESSARY	650.00	-
1	REAR LUGGAGE BOX (SN)	CUT	280.00	250.00
			930.00	250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR TO REPAIR THE FRT SAFETY GUARD .		450.00	120.00
	TO REMOVE AND RENEW THE GEAR CHAIN REAR.	NOT NECESSARY	120.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	80.00	-
	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	100.00	-
	TO LIFT-UP ENGINE WITH GEARBOX AND REFIT THE SAME.	NOT NECESSARY	250.00	-
	TOWING CHARGES.		80.00	50.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF MAIN STAND AND REAR EXHAUST .		350.00	250.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		200.00	100.00
			1,630.00	520.00
	GRAND TOTAL		6,380.50	2,340.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CS/AGI20011694/Uvf3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.