

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20011696/UBS3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800155743

Claimant
Vehicle No : SLM9170Y **Insured Vehicle No :** FBN8844G

Date of Loss: 26/10/2020 **Nature of Claim:** TP **Claim No:** 7083591673SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM9170Y		
Make & Model:	CHEVROLET ORLANDO, 1.4 Turbo (A)	Engine No:	B14NET163190620
Reg. Date:	17/04/2017 (Man. Year: 2017)	Chassis No:	KL1YA7589HK610531
Colour:	White	Odometer:	48535 km
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,246.00	9,340.50	11,905.50	56.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	1,950.00	1,770.00	47.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,966.00	11,290.50	13,675.50	54.78
Approved Total (Overridden) (\$\$)		9,000.00		
(\$\$)	24,966.00	9,000.00	15,966.00	63.95
+ GST 7.00/7.00% (\$\$)	1,747.62	630.00	1,117.62	63.95
Nett Amount (\$\$)	26,713.62	9,630.00	17,083.62	63.95
+ Loss of Use (5.0 x S\$60.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		9,932.00		
Global Sum Settlement (\$\$)		9,800.00		

INSPECTION

Date of Assignment: 27/10/2020

Date Inspected: 27/10/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Deformed / Warped	2,055.00 F	*1,820.00 FL
2	1		*REAR BUMPER LOWER	Distorted	1,450.00 F	*1,120.00 FL
3	1		*REAR BUMPER CENTRE LOWER (SILVER)	Torn	650.00 F	*480.00 FL
4	1		*REAR BUMPER TOP GARNISH	Distorted	450.00 F	*250.00 FL
5	1		*REAR BUMPER TOW COVER	Deformed	38.00 F	*38.00 FL
6	1		*REAR BUMPER REFLECTORS	O/S Cracked	210.00 F	*102.00 FL
7	1		*REAR BUMPER REVERSE LAMP	Cracked	420.00 F	*395.00 FL
8	4		*REAR BUMPER REVERSE SENSORS	Serviceable	780.00 F	*- FL
9	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
10	1		*REAR BUMPER INNER TOP RETAINER	Cracked	299.00 F	*225.00 FL
11	1		*TAILGATE	Badly Dented	2,990.00 F	*2,100.00 FL
12	1		*TAILGATE OUTER CHROME HANDLE	Serviceable	415.00 F	*- FL
13	1		*TAILGATE CHEVROLET EMBLEM	Necessary	68.00 F	*68.00 FL
14	1		*TAILGATE OPLANDO EMBLEM	Necessary	65.00 F	*65.00 FL
15	1		*TAILGATE TURBO EMBLEM	Necessary	59.00 F	*59.00 FL
16	1		*TAILGATE REFLECTORS	O/S Scratched	1,300.00 F	*390.00 FL
17	1		*TAILGATE INNER LOCK	Shorted / Jammed	315.00 F	*288.00 FL
18	1		*TAILGATE INNER TRIM BOARD	Cracked	882.00 F	*488.00 FL
19	1		*TAILGATE WEATHERSTRIP	Twisted	398.00 F	*269.00 FL
20	1		*REAR WINDSCREEN	Not Necessary	980.00 F	*- FL
21	1		*REAR WINDSCREEN MOULDING	Necessary	96.00 F	*96.00 FL
22	2		*TAILLAMPS	Not Necessary	1,770.00 F	*- FL
23	1		*REAR END PANEL	Badly Dented	970.00 F	*825.00 FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	355.00 F	*315.00 FL
25	1		*REAR FLOOR PANEL	Repair	1,420.00 F	*- FL
26	1		*REAR FLOOR PANEL TOP TOOLS BOX	Cracked	850.00 F	*752.00 FL
27	1		*REAR EXHAUST	Not Necessary	1,090.00 F	*- FL
28	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	311.00 F	*- FL
29	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
30	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
31	1		*REAR LICENCE PLATE W/HOLDER	Damaged	50.00 FS	*40.00 FS
32	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
34	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,246.00	10,355.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,014.50
Total Parts (\$\$)	21,246.00	9,340.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
7	TO SPRAY RUST PROOFING	New	120.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	950.00
Gross Labour Cost (\$)			3,720.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >