



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 7574E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (AMG C63)	DEFORMED	2,200.00	1,800.00
1	REAR BUMPER CARRIER BRACKET	NOT NECESSARY	230.00	-
1	REAR BUMPER CARRIER	BENT	520.20	520.20
1	REAR BUMPER LOWER DEFUSER	NOT NECESSARY	455.00	-
1	FRONT PASSENGER SEAT HEAD REST	NOT NECESSARY	655.00	-
	LESS 10% DISCOUNT		-	-232.02
			4,060.20	2,088.18
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DRIVER SEAT HEAD REST (SN) (LOCAL REPAIR)	ACTIVATED	655.00	250.00
			655.00	250.00
	<u>LABOUR</u>			
	LABOUR TO RE-SPRAY REAR BUMPER.		300.00	200.00
	TO PANEL BEATING / REMOVE & INSTALL NEW PARTS.		300.00	200.00
			600.00	400.00
	GRAND TOTAL		5,315.20	2,738.18
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (UN-CONFIRMED)			2,200.00

Report Ref No. CS3/LCR17015455/Gyd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.